			Form approved.
Form 3160-5	UN ED STATES	H. H. SUBLIT IN CAMP	Budget Bureau No. 1004-0135
(November 1983) (Formerly 9-331)	DEPARTMENT OF THE INT	(Oab 1	
(Polinetry 9=331)	BUREAU OF LAND MANAGE	ting to the state of the state	.h 1111 - 1 - 1 - 1
	BUREAU OF LAND MANAGE	WE'N TIE OF TAF D	6. LF INDIAN, ALLOTTEE OR TRIBE NAME
SUN	DRY NOTICES AND REPOR	TS ON WELLS	OF THUTAN, ADDUTTED OR TRIBE NAME
	form for proposals to drill or to deepen or	ping back to a different reservoir.	
	Use "APPLICATION FOR PERMIT-" for	auca proposition / 10 57 M 10	7 7 7
1. OIL GAS		O STATE OF	7. UNIT AGREEMENT NAME
WELL WELL	OTHER	CAR.	
2. NAME OF OPERATOR	0 1	ANLA ST	8. FARM OR LEASE NAME
Union Vil	Company of Lali	tornia	North Maduro ted. Uni-
3. ADDRESS OF OPERATOR	· - · · / / / / · · - ·		9. WHLL NO.
PO. Box	671 - Midland, lex	as 79702	
4. LOCATION OF WELL (R See also space 17 belo	eport location clearly and in accordance wit	th any State requirements.	10. FIELD AND POOL, OR WILDCAT
At surface	Uni+ H		Gem Morrow
22101	THE LING TEL AS	$S_{ec}$ . $20$	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
2010	FNL & 660' FEL of	766.20	0
	•		Dec. 20 T-19.5 R-33-F
14. PERMIT NO.	15. ELEVATIONS (Show whe	ther DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
	3620.6	' CP	NM جما
16.	Check Appropriate Box To Indic	ate Nature of Notice, Report, or	Other Data
NOTICE OF INTENTION TO: SUI		QUENT REPORT OF:	
		1	
TEST WATER SHUT-OF		WATER SHUT-OFF	REPAIRING WELL
FRACTUBE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR CIDIZING	ABANDONMENT*
REPAIR WELL	CHANGE PLANS	(Other) 1817	ts of multiple completion on Well
(Other)			pletion Report and Log form.)
17. DESCRIBE PROPOSED OF proposed work. If nent to this work.)	COMPLETED OPERATIONS (Clearly state all pewell is directionally drilled, give subsurfact)	ertinent details, and give pertinent date be locations and measured and true verti	s, including estimated date of starting any cal depths for all markers and zones perti-
89LOADED 2-3/8" TBG W	/53 BFW. EST PI RATE INTO PERFS 13	,589-13,602', 13,606-18' @ 1.6 BP	M @ 4400 PSI. RAN & SET OTIS 1.875
BLANKING PLUG IN OT	IS WB PKR # 13,548'. TSTD PLUG TO :	3800 PSI, OK. MIRU DIAMOND WELL	SERVICE. NU BOP. TSTD BOP TO 500
OK CHES F-LYL IN	TBG TO 10,500', NO FLUID ENTRY. LO	ADED TBG. REL FROM PKR. POOH, I	NC. SDON.
99FINISH POOH W/PROD	TBG & SEAL ASSY. RAN & DUMPED 3 SX	S CMT ON PKR & 13,529'. TOC & 13	,509'. RIH W/4-3/4" BIT ON 2-3/8"
87 FIH W/4-3/4" BIT ON	2-3/8" TBG TO TOC & 13,510' ETD.	DIL TO 12 425' CDOT 600 CAL 10W	ACETTO 1010 12 405 10 0101
	T EXCESS ACID & CIRC HOLE W/300 BBL		
99 501 417 470 118 X NI	PPLE 6 13,170', X NIPPLE 6 13,179'.	BTM OF MULE SHOE GIJIDE 4 13,181	L'. SCION.
	IS (13,142') 2-3/8" 4.7# N-80 BRD EU	IE "AB" MODIFIED TBG (# 13,154'. A	ALL TBG TSTD TO 6000 PSI. NU
	W/71,000 SCF OF N2 6 0-3200 PSI.	LATCHED INTO OTIS "WB" PKR 6 13,1	154'. LANDED TBG & TSTD
	ULUS TO 500 PSI, OK. SDON.		
ST BLED NZ IN TBG TO 3	0000 PSI. PERF'D MIDDLE MORROW W/1-	11/16" STRIP GUN 4 SPH 13,252-13,	346' (119 SHOTS), INCOMP. SDON
SITP 2900/14 (N2).	RIH W/PERF GUN SET DN @ 12,700'.	PICKED UP & GUNS STUCK. WORKED	GUN FOR 4 HRS & COULD NOT WORK EDGE
SECO PICES OFF MELL	. 2900-0 PSI. COULD NOT WORK GUNS F	REE. SDON.	
-89SITP 200/13-1/2.	LOADED TBG W/46 BBLS 6% KCL WTR. PL	IIIED 2600 LBS ON MIDE IN 2 DEDE	CUN CAME LOOF
OK. RIH W/CCL TO	14,400' OK. NO TREE. REL FRM PKR.	STEEL 2 2/0" TRO WINE EN & PERF	GUN CAME LOUSE. POOH W/WL & ALL GUN
13,154'. NU TREE.	TSTD 2-3/8" X 5-1/2" ANNULUS TO 80	0 DC	Z & U-4000 PSI. LATCHED INTO PKR @
-89 BLED TBG PRES TO 20	100 PSI (N2). PERF MIDDLE MORROW W/	JU FSI, UK. SDUN. /1-11/16" STRID GHN 4 SDE 12 410-:	13.435 (49 SHOTS). TOTAL SHOTS IN

Engineer DATE CONDITIONS OF APPROVAL, IF ANY:

MIDDLE MORROW 197 SHOTS. NO CHANGE IN PRES. FLWD WELL DN ON 18/64" CK, PRES 2000-0 PSI. GAS TO SURF IN 56 MINS TSTM.

SERVICE \*See Instructions on Reverse Side