

SUNDRY NOTICES AND REPORTS ON WELLS

(This form for use by permittees to report on the progress of work on wells or to report on the results of operations on wells. It is to be filled out by the permittee and submitted to the Bureau of Land Management, Department of the Interior, Washington, D.C. 20540.)

APPLICATION FOR PERMIT - For new permits.

ON ☒ WELL ☐ GAS ☐ OTHER

NAME OF OPERATOR

Siete Oil & Gas Corporation

ADDRESS OF OPERATOR

P. O. Box 2523 Roswell, New Mexico 88202

LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 11 below.)

1943' FWL & 1980' FNL SE/4 NW/4

14. PERMIT NO.

API # 30-025-30323

15. ELEVATIONS (Show whether of, to, or from.)

3760' GR

1. DATE OF REPORT

2. NAME OF LEASE

Inea Federal

3. WELL NO.

8

16. NAME AND LOCATION OF WELL

Young North Bone Spring

17. SEC., T., R., S., OR B.M. AND QUARTER OR AREA

Sec. 17: T18S, R32E

18. COUNTY OR PARISH

Lea

19. STATE

NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

FILL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANE

CONSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

Amended T.D.

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completions on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details and give pertinent dates including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and open parts down to this work.)

4/15/88 Amend T.D. from 9200' to 9400'

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Production/Reservoir Engineer

DATE

4/15/88

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

535

RECEIVED

APR 27 1988

OCD
HOEBS OFFICE