

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-30360
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. K-6119
7. Lease Name or Unit Agreement Name Betty State
8. Well No. 2
9. Pool name or Wildcat North Vacuum Atoka-Morrow

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER
2. Name of Operator C. W. Trainer
3. Address of Operator c/o Oil Reports & Gas Services, Inc. Box 755, Hobbs, NM
4. Well Location Unit Letter I : 1980 Feet From The South Line and 660 Feet From The East Line Section 16 Township 17S Range 35E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3959 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pull tubing & packer. Ran tubing open ended. Circulate hole with 25#/bbl gelled water. Spotted cement plugs as follows:

1. From 11,700 to 11,800 with 20 sacks. WOC 1 hour, tag top of plug at 11,700.
2. From 9975 to 10,081 with 15 sacks
3. From 6180 to 6280 with 15 sacks
4. From 3493 to 3593 with 15 sacks
5. From 1511 to 1611 with 15 sacks
6. From 82 to surface with 10 sacks. Install dry hole marker. Well plugged and abandoned 9/7/89.

Location will be cleared and levelled & made ready for inspection.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE <u>Wendy D. Hall</u>	TITLE <u>Agent</u>	DATE <u>9/11/89</u>
TYPE OR PRINT NAME	TELEPHONE NO.	

(This space for State Use)	OIL & GAS INSPECTOR	APR 11 1997
APPROVED BY <u>Chad Perrin</u>	TITLE <u>Inspector</u>	DATE
CONDITIONS OF APPROVAL, IF ANY:		

✓
R

5

RECEIVED

SEP 13 1969

GOO

HOBBS OFFICE