(Formerly 9-331)	DEPARTME! OF THE INT		re Expires August 31, 1985
SUN (Do not use this	DRY NOTICES AND REPORT form for proposals to drill or to deepen or p Use "APPLICATION FOR PERMIT—" for as	IS ON WELLS HEXICO 83	NM-56749 3240 IF INDIAN, ALLOTTEE OR TRIBE NAME
1.			7. UNIT AGREEMENT NAME
WELL WELL 2. NAME OF OPERATOR	OTHER		8. FARM OR LEASE NAME
Texaco Prod	ucing Inc.		Federal (USA) "L"
3. ADDRESS OF OPERATOR			9. WELL NO.
PO Box 728, 4. Location of Well (R. See also space 17 belo At surface	eport location clearly and in accordance with	any State requirements.*	1 10. FIELD AND POOL, OR WILDCAT Tonto Seven Rivers
Unit Letter	J, 2310' FSL & 1650'	FEL	11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA
14. PERMIT NO.	15. ELEVATIONS (Show whether	er DF, RT, GR, etc.)	Sec. 14, T19S, R331
	3689' GR (1:	3' KB)	Lea NM
16.	Check Appropriate Box To Indicat	e Nature of Notice, Report, or	Other Data
Ne	OTICE OF INTENTION TO:	1	QUENT REPORT OF:
TEST WATER SHUT-OF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
PRACTURE TREAT	MULTIPLE COMPLETE	i-	ALTERING CASING
SHOOT OR ACIDIZE REPAIR WELL	ABANDON* CHANGE PLANS	SHOOTING OR ACIDIZING (Other)	ABANDONMENT*
(Other)		(NOTE: Report result	ts of multiple completion on Well pletion Report and Log form.)
	COMPLETED OPERATIONS (Clearly state all perti- well is directionally drilled, give subsurface	inent details, and give pertinent dates locations and measured and true vertices	s, including estimated date of starting any cal depths for all markers and sones perti-
3815'. on 5/1/ 3) Spot 12 4) Perf Se 5) Acidize	25 gallons of 10% aceti even Rivers interval 37 e perfs with 3000 gallo	osi. Tested from 8: 1c acid from 3625'-1722'-3750' at 1 SPF 15 ons 15% NEFE and 58	:45 AM to 9:15 AM 3750'. (29 holes). RCN ball sealers.
lbs. sa 7) Clean c 8) GIH wit 9) On 24 h 114 BLW	re treat perfs with 350 and. Shut in. Out sand to PBTD 3815'. The production equipment to production ending 2 and 50 and	e:00 PM on 5/8/89. 9.	Pumped 212 BO and Pumped 212 BO
lbs. sa 7) Clean of 8) GIH wit 9) On 24 h 114 BLW	re treat perfs with 350 and. Shut in. Dut sand to PBTD 3815'. The production equipment about potential ending 2 V. GOR-1108. GRAV-31.	2:00 PM on 5/8/89. 9.	Pumped 212 BO and AC TO THE CETYED RECEIVED
lbs. sa 7) Clean of 8) GIH wit 9) On 24 h 114 BLW I hereby certify that the SIGNED J.A. H	re treat perfs with 350 and. Shut in. Out sand to PBTD 3815'. The production equipment about potential ending 2 W. GOR-1108. GRAV-31.	e:00 PM on 5/8/89. 9.	Pumped 212 BO and AC TO THE CONTROL OF T
lbs. sa 7) Clean of 8) GIH wit 9) On 24 h 114 BLW	re treat perfs with 350 and. Shut in. Out sand to PBTD 3815'. The production equipment about potential ending 2 W. GOR-1108. GRAV-31.	571 bbs Area Superinten	Pumped 212 BO and AC TO THE CONTROL OF T
lbs. sa 7) Clean of 8) GIH wit 9) On 24 h 114 BLW	e treat perfs with 350 and. Shut in. Out sand to PBTD 3815'. The production equipment about potential ending 2 and correct 397-3. TITLE HOLE Or State office use)	571 bbs Area Superinten	Pumped 212 BO and Pumped 212 BO

*See Instructions on Reverse Side

SJ: