

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator TXO Production Corp.		8. Farm or Lease Name Penron-Byers
3. Address of Operator 900 Wilco Bldg. Midland, TX 79701		9. Well No. #1
4. Location of Well UNIT LETTER <u>P</u> <u>810</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>3</u> TOWNSHIP <u>17-S</u> RANGE <u>37-E</u> NMPM.		10. Field and Pool, or Wildcat Shipp Strawn
15. Elevation (Show whether DF, RT, CR, etc.) 3762.8 GL		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-24-88 Drlg 7 7/8" hole.
thur
6-09-88
6-10-88 Fishing for stuck DC. Ran free point. Spot oil & TIH w/grapple bumper sub.
6-11-88 TIH w/back off shot. Stuck shot inside DC. Work free. TOH w/line. Left primer
cord shot in DC. TIH w/new shot. Spot 3 BBL mud pile. Chain OOH, rec 4 DC.
Screw into fish @ 9275'. TIH w/spud bars. Spud primer cord & spot line.
6-12-88 Jar on tools. Ran free pt. TOH w/free pt. SLM out hole. LD fishing tools, rec 11
DC. TIH. Jar on fish.
6-13-88 Jar on fish. Circ & cond. mud. TIH w/washover shoe, wash pipe. bumper sub,
jars.
6-14-88 TIH w/wash pipe. Washover fish. Chain OOH. TIH w/screw in sub, bumper sub,
jars. Screw into fish. TOH.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Beth Cune TITLE Secretary DATE 6-15-88

APPROVED BY [Signature] TITLE [Signature] DATE [Signature]

CONDITIONS OF APPROVAL, IF ANY: