

FORM 8-81)

DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different formation.
See "APPLICATION FOR PERMIT—" for such proposals.)

WATER WELL ☒ GAS WELL ☐ OTHER ☐

NAME OF OPERATOR
Siete Oil & Gas Corporation

ADDRESS OF OPERATOR
P.O. Box 2523
Roswell, NM 88202-2523

LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 13 below.)
At surface 330' FSL & 2310' FWL, SE $\frac{1}{4}$ SW $\frac{1}{4}$, Unit Letter N

PERMIT NO
30-025-30445

16 ELEVATIONS (Show whether SP, BP, OR OR.)
3792' GR

NM-17807

1. IF PERMITS, ALLOWED (In State Wells)

2. DATE OF PERMIT DATED

3. NAME OF LAND OWNER
Quanah Federal

4. WELL NO.
1

10. FORM AND TYPE OF WORK
Quevedo Plains upper B S
Young Wolfcamp

11. SEC. T. R. S. OR B.M. AND
COUNTY OR STATE
Sec. 14: T18S, R32E

12. COUNTY OR PARISH
Lea

13. STATE
NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER DEPTH-OUT

FRACURE TREATMENT

SHOOT OR ACIDIZING

REPAIR WELL

(Other)

WELL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANE

COMPLETION REPORT OF:

WATER DEPTH-OUT

FRACURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completions on Well Completion or Recompletion Report and Log form.)

DETAILED PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates including estimated date of starting any proposed work. If well is directionally drilled, give subsurface latitudes and measured and true vertical depths for all markers and open parts (omit in this work).)

10/07/88

RU Schlumberger and perfed interval as follows: 10818', 10819', 10820', 10821', 10822', 10823', 10824', 10856', 10857', 10858, 10859' & 10860' w/12 perfs, TIH w/tbg & treating pkr, RU Dowell Schlumberger & spot 2 bbls 7 $\frac{1}{2}$ % acid over perfs, set pkr @ 10765', formation broke @ 4040 PSI @ .6 BPM, SK to open bypass on pkr, pumped acid to pkr, close bypass, acidize w/5000 gal 20% HCL, AFR-2.6 BPM, AIP-5000, balled out to 6100 PSI, FPIP-5480, ISIP-5000, @ 5 min-4730, @ 10 min-4640, @ 15 min-4570, flowback & swab test well.

CONFIDENTIAL

RECEIVED
OCT 19 11 01 AM '88
CARLSBAD FIELD OFFICE
AREA RECORDERS

I hereby certify that the foregoing is true and correct

SIGNED Cathy D. Batley

TITLE Drilling/Production Secretary

DATE 10/12/88

(This space for Federal or State office use)

ACCEPTED FOR RECORD

APPROVED BY _____

TITLE _____

DATE OCT-31 1988

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

SJS
CARLSBAD, NEW MEXICO

RECEIVED
FEB 16 1990