

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
ALBUQUERQUE, NEW MEXICO 88240

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir
Use "APPLICATION FOR PERMIT-" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☒ Other P & A' D

2. Name of Operator

Harvey E. Yates Company

3. Address and Telephone No.

P.O. Box 1993, Roswell, NM 88202 1-505-623-6601

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

330' FSL & 2310' FEL
SEC. 8, T-18S, R-32E

5. Lease Designation and Serial No.

NM-77315

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

AMOCO CP "8" FEDERAL #2

9. API Well No.

30-025-30562

10. Field and Pool, or Exploratory Area

YOUNG GRAYBURG

11. County or Parish, State

LEA

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

- ☐ Notice of Intent
☒ Subsequent Report
☒ Final Abandonment

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other TESTING & P&A

- ☐ Change in Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log Form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

CURRENT PERFS (4488-4703.5' OA) GRAYBURG
6/29/93 SET CIBP @ 4450'.
6/30/93 RU WEDGE & DUMP 50' CMT ON TOP OF CIBP @ 4450'. NEW PBTD @ 4400'.
PERF PREMIER 4240-50' (4 JSPF 40 HOLES)
SPOT 150 GALS 20% NEFE. BREAKDOWN PERFS. FOLLOW WITH 1850 GALS
SAME ACID AND BALL SEALERS.
7/2/93 RU WEDGE AND SET CIBP @ 4200'.
PUMP 50' CMT PLUG ON TOP OF CIBP @ 4200'. (PBTD @ 4150').
ROLL HOLE WITH SALT WATER GELL.
7/3/93 RU CSG JACKS & FREE POINT & CUT CSG @ 2109'. (APPROVED BY BLM)
SPOT 65 SACK PLUG @ 2183'. WOC 4 HOURS. TAG CMT @ 1905'.
7/4/93 SPOT 100' PLUG FROM 1135' TO 1035'. SPOT 100' PLUG FROM 471' TO 371'.
SPOT-50' PLUG AT SURFACE. INSTALL DRY HOLE MARKER.

Approved as to plugging work.
Liability under bond is retained until
surface restoration is completed.

14. I hereby certify that the foregoing is true and correct

Signed Ray F. Nokes Title PROD. MGR/ ENG. Date 7/14/93

(This space for Federal or State office use)

Approved by (Off. Seal) JOR G. TARA Title PETROLEUM ENGINEER Date AUG 6 - 1993
Conditions of approval, if any: