

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-30592
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
F & M Oil and Gas Company

3. Address of Operator
P.O. Box 891; Midland, Texas 79710

4. Well Location
Unit Letter J : 2086 Feet From The South Line and 1980 Feet From The East Line

Section 13 Township 17S Range 38E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3682 GR

7. Lease Name or Unit Agreement Name Holloway, F. M.
8. Well No. #1
9. Pool name or Wildcat Knowles Devonian South

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: ☐	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 4-21-97 Notified OCD. RIH w/ gauge ring, unable to get below 4439'. Start in hole w/ tbg.
4-22-97 Contacted OCD. RIH w/ tbg to 11,487' as per Jerry Sexton. Pumped mud and 30 sx C cmt. WOC, no tag. Pumped mud and 30 sx C cmt. WOC & tagged @ 11,217'.
4-23-97 Contacted Charlie Perrin w/ OCD. Pumped 25 sx C cmt 8500-8253'. Pumped 30 sx cmt w/ CaCl₂ @ 5059'. Tagged plug @ 4762'. Cut csg @ 3551'. Unable to pull csg.
4-24-97 Contacted OCD. Could not pull csg; cut @ 3514'. Could not pull csg. Pumped 30 sx C cmt @ 3600'. WOC.
4-25-97 Tagged plug @ 3320'. Cut csg @ 2994'; unable to pull csg.
4-28-97 Contacted Bonnie w/ OCD. Perfed csg @ 3020'; set packer, no rate @ 2000 psi. Pumped 25 sx C cmt w/ CaCl₂ @ 3087', got OK not to tag from Jerry Sexton. Pumped 25 sx C cmt 2327-2075'. Cut csg @ 407'; set packer, no rate. Pumped 25 sx C cmt 467-220'. Pumped 5 sx C cmt 20'-surface. Procedures OK'd by Gary Wink, OCD.
5-02-97 Cut off wellhead & capped well. Covered pit and dug up dead men. Installed dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE President DATE 5-20-97

TYPE OR PRINT NAME [Signature] TELEPHONE NO 915-682-7711

(This space for State Use)

APPROVED BY [Signature] OIL & GAS INSPECTOR [Signature] DATE SEP 15 1997

CONDITIONS OF APPROVAL, IF ANY:

JC mP BR