

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-30669
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name  Price Family 1L
2. Name of Operator Nearburg Producing Company	8. Well No. 1
3. Address of Operator P. O. Box 31405, Dallas, Texas 75231-0405	9. Pool name or Wildcat Shipp Strawn
4. Well Location Unit Letter <u>L</u> : <u>660</u> Feet From The <u>west</u> Line and <u>2130</u> Feet From The <u>south</u> Line Section <u>1</u> Township <u>17S</u> Range <u>37E</u> NMPM <u>Lea</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3746.4' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: Additional perforations <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

02/15/90 POOH w/rods and pump.  
02/16/90 GIH open ended w/2-7/8" tbg (11,680'). Spot 200 gals 10% MSA from 11,680'-11,480'. POOH.  
02/17/90 Perf lower Strawn from 11,676'-11,662' (2 SPF, 29 holes). PU Baker 2-7/8"x5-1/2" Model R DG pkr, 2-7/8" standard SN, and 380 jts 2-7/8" N-80 tbg. Set pkr @ 11,630'.  
02/19/90 Acidize Strawn perfs from 11,662'-11,676' w/500 gals MOD 202 w/14 ballsealers. Began swabbing.  
02/24/90 GIH & perf middle Strawn @ 11,637'-11,650', 11,619'-11,629', and 11,604'-11,610' (2 SPF, 61 holes) w/4" csg gun.  
02/26/90 Acidize Strawn perfs from 11,604'-11,676' w/3500 gals MOD 202 w/2 salt blocks.  
02/27/90 Swabbing well.  
03/01/90 Put well on rod pump.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Machelle Byrum TITLE Production Secretary DATE 3/6/90

TYPE OR PRINT NAME Machelle Byrum TELEPHONE NO. 214/739-1778

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT I SUPERVISOR TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

**MAR 12 1990**