

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		5. LEASE DESIGNATION AND SERIAL NO NM 40456	
2. NAME OF OPERATOR Harvey E. Yates Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P.O. Box 1933, Roswell, New Mexico 88202		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit letter G, 1650' FNL & 1650' FEL		8. FARM OR LEASE NAME Chevron 12 Federal	
14. PERMIT NO 30-025-30682		9. WELL NO. #5	
15. ELEVATION (Show whether DT, RT, GR, etc.) 3881.3 GL		10. FIELD AND POOL, OR WILDCAT North Young Bone Spring	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 12, T18S, R32E	
		12. COUNTY OR PARISH Lea	13. STATE NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT OFF	☐	PULL OR ALTER CASING	☐
FRACTURE TREAT	☐	MULTIPLE COMPLETE	☐
SHOOT OR ACIDIZE	☐	ABANDON*	☐
REPAIR WELL	☐	CHANGE PLANS	☐
(Other)	☐		☐

SUBSEQUENT REPORT OF:

WATER SHUT OFF	☐	REPAIRING WELL	☐
FRACTURE TREATMENT	☐	ALTERING CASING	☐
SHOOTING OR ACIDIZING	☒	ABANDONMENT*	☐
(Other) Cmt csg	☐	PUT ON PRODUCTION	☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS* (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

2-21-90 Perf: 8497-8505' (OA)
2-22-90 Acdz 8497-8505' w/2000 gals 20% NEFE w/3% acetic.
2-25-90 Set CIBP @ 8600'
2-27-90 Sqz perfs 8497 - 8505', drill out & circ hole to 8600'
3-3-90 Abrasa jet 4 holes @ 8495', acdz w/1000 gals 20% HCL
3-7-90 Run tbq and SN @ 8565', put back on production

18. I hereby certify that the foregoing is true and correct

SIGNED *Jim W. Skem*

TITLE Engineer
skh

DATE 3-29-90

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side