

DISTRICT I  
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

## OIL CONSERVATION DIVISION

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO. 30-025-30704
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Sharp Shooter 2 State
8. Well No. 2
9. Pool name or Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> Plugged & Abandoned	
2. Name of Operator Santa Fe Energy Resources, Inc.	
3. Address of Operator 550 W. Texas, Suite 1330, Midland, TX 79701	
4. Well Location Unit Letter <u>H</u> : <u>2310</u> Feet From The <u>North</u> Line and <u>330</u> Feet From The <u>East</u> Line Section <u>2</u> Township <u>18S</u> Range <u>32E</u> NMPM <u>Lea</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3899' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

### SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10/23/97: MIRU. Circulate hole w/ plugging mud. RU WL. RIH w/ CIBP. would not go. Made bit run. Set CIBP, capped well off.

10/24/97: ND WH, welded on 5-1/2" pull nipple. Pull csg slips out. Cut casing off at 2700'. Pulled & LD 63 jts.

10/25/97: RIH w/ tbg to 2800'. Mixed & pumped 45 sx C-Neat from 2800'-2600'. WOC 4 hrs, tagged plug at 2560'. Pull up hole to 516'. Mixed & pumped 60 sx C-NBeat from 516'-316' in 8-5/8" csg. POOH w/ tbg. Mixed & pumped 25 sx C-Neat cmt to surface (50' surface plug) in 8-5/8" csg. RD.

10/28/97: Cut off wellhead and welded on P&A marker. Cleaned location. Well is plugged and abandoned.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry McCullough TITLE Sr. Production Clerk DATE 11/4/97  
TYPE OR PRINT NAME Terry McCullough TELEPHONE NO. 915/687-3551

(This space for State Use)

APPROVED BY [Signature] TITLE [Signature] DATE 11/4/97  
CONDITIONS OF APPROVAL, IF ANY