

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-30759
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-1404-4
7. Lease Name or Unit Agreement Name	
Vacuum ABO Unit Tract #7	
8. Well No.	#5
9. Pool name or Wildcat	

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Phillips Petroleum Company	
3. Address of Operator 4001 Penbrook Street, Odessa, Texas 79762	
4. Well Location Unit Letter <u>P</u> : <u>850</u> Feet From The <u>South</u> Line and <u>850</u> Feet From The <u>East</u> Line Section <u>27</u> Township <u>17-S</u> Range <u>35-E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3940' RKB - 3925.4' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <u>Acidize</u> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-10-91 MI AND RU DDU. COOH with rods. Install BOP. Tag @ 8871, COOH with tubing.  
12-11-91 GIH with 2-7/8" tbg. and 5-1/2" packer. Set packer at 8650', Swab.  
12-12-91 MI & RU charger to pump matrix acid job w/total of 500 gallons 15% NEFE HCL containing LST & fines.  
12-13-91 Pulled tubing, removed packer, went back in with seating nipple & rods. Hung well back on.  
12-15-91 Pumped 2.71 Oil, 2.72 Water, 1.0 MCF, Temporary Drop From Report.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L.M. Sanders TITLE Supervisor Reg/Proration DATE 1-7-91  
TYPE OR PRINT NAME L.M. Sanders (915) TELEPHONE NO. 368-1488

(This space for SIGNATURE SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

JAN 09 '92