

Form 3160-5
(July 1989)
(Formerly 9-331)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CONTACT RECEIVED
OFFICE FOR NUMBER
OF COPIES REQUIRED
(Other instructions on reverse
side)

BLM Roswell District
Modified Form No.
NM060-3160-4

5. LEASE DESIGNATION AND SERIAL NO.

NM-56745

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals.)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Meridian Oil Inc.

8. FARM OR LEASE NAME

Shinnery Federal

3. ADDRESS OF OPERATOR

P.O. Box 51810, Midland, TX 79710-1810

3a. AREA CODE & PHONE NO.

915-686-5681

9. WELL NO.

5

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1650' FNL & 2310' FWL

10. FIELD AND POOL, OR WILDCAT
West Corbin (Delaware)

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 13, T18S, R32E

14. PERMIT NO.

30-025-30766

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3845' GR.

12. COUNTY OR PARISH

Lea

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐
☒

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other) Add Pay

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

☐
☐
☐
☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Drill two CIBP's at 5400' and 6300'. Push to PBTD at 6950'. TIH w/6500' of 2-7/8", 6.5# tubing and TAC.
Set TAC at 4980' (above Delaware perfs). Set SN @ 6500' (below the Massive Delaware perfs).
Set 2-1/2" x 1-1/4" x 24' RHBM pump. Test well. Turn to production.

18. I hereby certify that the foregoing is true and correct.

SIGNED

TITLE

Reg. Compliance Rep.

DATE

915-686-5681

(This space for Federal or State office use)

APPROVED BY

TITLE


DATE

8-20-91

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

SHINNERY FEDERAL #5
WEST CORBIN (DELAWARE) FIELD
 LEA COUNTY, NEW MEXICO
 EXISTING SCHEMATIC



TD:8711'/PBTD:8667'

7/22/91 DDC

Production Asst. IV, II (Measurement)

Responsibilities are:

- Editing charts, processing analysis, updating equipment changes.
- Instructing charts, LTD. as to the procedure to follow when integrating charts.
- Balancing gas systems prior to reporting integrated volumes.
- Auditing reporting volumes which affect the settlement process.
- Uploading integrated volumes to mainframe each month in a timely manner.
- Provide NGL in Houston with liquid reports.

Gas Systems Responsible for:

Benedum Plant
Morgan Creek Pipeline
Motran Pipeline
Flint
Sonora Gathering
Pitchfork
Canyon Ranch
Ward
Lea County
Edwards-Hough
Baker
Todd
*Cedar Cove
*Rosa Unit

Brunson
Puckett
*Panoma
*Quinlan
*Val Verde

* These Systems are not in the Midland Region