

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CONTACT RECEIVING
OFFICE FOR NUMBER
OF COPIES REQUIRED
(Other instructions on reverse
side)

BLM Roswell District
Modified Form No.
NM060-3160-4

5. LEASE DESIGNATION AND SERIAL NO.
NM-56745

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

7. UNIT AGREEMENT NAME

2. NAME OF OPERATOR

Meridian Oil Inc.

8. FARM OR LEASE NAME

Shinnery Federal

3. ADDRESS OF OPERATOR

21 Desta Dr., Midland, TX 79705

3a. AREA CODE & PHONE NO.

915/686-5600

9. WELL NO.

5

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1650' FNL & 2310' FWL Sec. 13, T18S, R32E

10. FIELD AND POOL, OR WILDCAT

~~Shinnery~~ (Delaware)

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 13, T18S, R32E

14. PERMIT NO.

Approved 12/20/89

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3845' GR.

12. COUNTY OR PARISH

Lea

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) **Abandon Bone Spring**

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☒

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Abandon the Bone Spring. RIH w/5 1/2" CIBP & set at 6300'. Perf. 8 holes @5500'. Unable to pump cmt @3000 psi. Ran CBL from 6000' to 1900'. TOC @2270'.

RIH w/5 1/2" CIBP & set @5400'. Prepare to move to Delaware to perf and stimulate.

ACCEPTED FOR FILING
Am

CALISBAD, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Robert L. Bradshaw

TITLE

Sr. Staff Env./Reg. Spec.

DATE

24 April 1990

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

***See Instructions on Reverse Side**