

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-30770
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Byers 12L
8. Well No. 1
9. Pool name or Wildcat Humble City Strawn, South

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Dry Hole	
2. Name of Operator Nearburg Producing Company	
3. Address of Operator P. O. Box 823085, Dallas, Texas 75382-3085	
4. Well Location Unit Letter L : 1,980 Feet From the south Line and 810 Feet From The west Line Section 12 Township 17S Range 37E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3,733.2' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6/29/92 Spotted 25 sx Class C cement plug at 6,975'.

6/30/92 RIH w/2-3/8" tbg and tagged cement at 6,933'. Circ salt gel mud to surface. Spot 35 sx plug at 4,700' (Class C cement plug).

7/01/92 Tagged cement plug at 4,555'. Spot 35 sx Class C cement plug at 2,193'. Cut off wellhead and spot 10 sx Class C cement plug from 30' to surface. Install dry hole marker, cut off wellhead, and clean location. Ray Smith and Charlie Perrin of NMOCDC witnessed the setting of all cement plugs.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Machelle Byrum TITLE Production Secretary DATE 7/31/92

TYPE OR PRINT NAME Machelle Byrum TELEPHONE NO. 214/739-1778

(This space for State Use)

APPROVED BY Ray W. Hill OIL & GAS INSPECTOR TITLE Inspector DATE 7/31/92

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

AUG 03 1992

OCD HOBBS OFFICE