

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Geology, Minerals and Natural Resources Department

Revised 1-1-89

DISTRICT I
P.O. Box 1930, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Artesia, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-02530961
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. 84286-1
7. Lease Name or Unit Agreement Name West Lovington Unit
8. Well No. 69
9. Pool Name or Wildcat West Lovington Upper San Andres
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 315.2 M.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator Greenhill Petroleum Corporation
3. Address of Operator 16010 Barkers Point, Ste., 325, Houston, TX 77079
4. Well Location Unit Sec. 0 : 0 Feet From The 0 Line and 0 Feet From The West Line Section 9 Township 15 Range 06 NMCN Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 315.2 M.

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPS. ☒ PLUG AND ABANDONMENT ☐
FULL OR ALTER CASING ☐ CASING TEST AND CEMENT JOB ☒ OTHER: ☐
12. Describe Proposed or Completed Operations (Clearly state all pertinent details; and if applicable, date; including estimated date of starting any proposed work) SEE RULE 1103. Well Spudded on 12-26-90 12-27-90/Drilling to 368. Circ. hole clean. Drop survey. POH. RU & ran 9 jts 8 5/8 24# K55 ST&C csg. Pipe set @ 368. Circ. M&P 275 sxs Class "C" + 2% CaCl2 @ 14.8 ppg. Bump plug w/ 900#. Floats held. 1-8-91 Ran 119 jts of 5 1/2"-15.5# J55 LT&C csg. Pipe set at 5240. TOFC @ 5192. C&C mud. RU Howco. M&P 785 sxs Class "C" + 2% CaCl2 at 14.8 ppg. Displace cmt. w/fresh water. Bump plug w/1800# at 1300 hrs. Release pressure. Floats held. OK. ND BOPS. Set 5 1/2 csg slips & cut 5 1/2 csg. Weld on belled nipple. Install cap.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Michael J. Newport TITLE Land Manager/Permian Basin DATE 3-13-91
TYPE OR PRINT NAME Michael J. Newport TELEPHONE NO. 955-1146

(This space for State Use)

APPROVED BY _____

TITLE _____

DATE _____

CONDITIONS OF APPROVAL, IF ANY: