

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-30968

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil / Gas Lease No.

548570

7. Lease Name or Unit Agreement Name

VACUUM GLORIETA WEST UNIT

8. Well No.

74

9. Pool Name or Wildcat

VACUUM GLORIETA

**SUNDRY NOTICES AND REPORTS ON WELL**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator  
TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator  
P.O. BOX 730, HOBBS, NM 88240

4. Well Location

Unit Letter G : 2310 Feet From The NORTH Line and 1900 Feet From The EAST Line  
Section 36 Township 17S Range 34E NMPM LEA COUNTY

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4001' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☒ ADDED PAY AND ACIDIZED FORMATION

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12/2/93 - 12/9/93

1. MIRU, TOH W/ PROD EQUIP, C/O TO 6239. SET RBP @ 6210', PLD UP TO 6190', SPTD 100 GALS 20% NEFE FR 6142'-6190'.  
SET PKR @ 6060', SQZD ADDL 100 GALS 20% NEFE INTO FORMATION.

2. ACIDIZED PERFS FR 6142'-6190' W/ 3500 GALS 20% NEFE, MAX P = 2550#, AIR = 4 BPM. SWABBED BACK LOAD.

3. RETRIEVED RBP & SET @ 6075', SPTD 4 BBLS ACETIC ACID, TOH W/ PKR.

4. RAN COLLAR LOG. PERFD W/ 2 JSPF FR 5940'-6019' (100 HLES). SET PKR @ 5780', LOADED BS W/ FW.

5. ACIDIZED PERFS FR 5940'-6019' W/ 4,500 GALS 20% NEFE. MAX P = 2550#, AIR = 4.5 BPM. SWABBED TSTD WELL.

6. RETRIEVED RBP & SET @ 5964', SWAB TSTD UPPER ZONE. TOH W/ RBP & PKR.

7. TIH W/ PROD EQUIP & RETURNED WELL TO PRODUCTION.

OPT 12/21/93 20 BOPD, 154 BWPD, 7 MCFD

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Monte C. Duncan TITLE Engr Asst

DATE 2/2/94

TYPE OR PRINT NAME Monte C. Duncan

Telephone No. 397-0418

**ORIGINAL SIGNED BY JERRY SEXTON**  
**DISTRICT I SUPERVISOR**

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_

DATE 2/2/94

CONDITIONS OF APPROVAL, IF ANY: