

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-30970
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil / Gas Lease No.	B-1056-1
7. Lease Name or Unit Agreement Name	VACUUM GLORIETA WEST UNIT
8. Well No.	48
9. Pool Name or Wildcat	VACUUM GLORIETA

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.	
1. Type of Well:	OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	PO BOX 3109 MIDLAND, TX 79702
4. Well Location	BHL: 283 FSL, 350 FWL Sec 30-175-350
Unit Letter	P
815 Feet From The	SOUTH Line and 800 Feet From The EAST Line
Section 25	Township 17S Range 34E NMPM LEA COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3990' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPERATION ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: ☐	HORIZONTAL COMPLETION ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-21-01: MIRU KEY #118. 4-22-01: TAG CIBP @ 5867'. MAKE 3' CORRECTION TO 5870'. RUN GYRO & ORIENT WHIPSTOCK. SET @ 88 DEG AZ. MILL FR 5857-5860, 5863, 5866. TOW @ 5857. BOW @ 5863. 4-24-01: DRILL 5866-5899, 5919, 5930, 6003, 6130, 6496, 6757, 6955.
4-29-01: TIH W/JARS & DC'S. LATCH OVER FSH. JAR FREE. TIH W/RBP & SET @ 5740. 5-03-01: MIRU KEY #319. 5-09-01: PU 3 1/2" TBG. LATCH ON RBP @ 5740. REL. SET PKR & TEST TO 800 PSI. INSTL FRAC TREE. SN @ 5744. PKR @ 5751. 5-12-01: ACID FRAC GLORIETA W/35,000 GALS 15% HCL. 5-13-01: TIH OPEN ENDED W/38 JTS 2 7/8" TBG & 1 STAND OF 3 1/2" TBG. 5-15-01: PU SANDLINE DRILL & TAG CIBP @ 5870. BREAK DN & CHASE TO 6000'. (PBD @ 5990) MI 2 7/8" TBG & TALLY. TIH W/MA. 2 7/8" TBG, TAC & SN. 5-16-01: NDBOP. SET TAC W/12 PTS TENSION. MA @ 5974. PERF SUB @ 5943. SN @ 5939. TAC @ 5778. TIH W/PMP & RDS. 5-18-01: SET PUMPING UNIT. 5-19-01: CONNECT POWER TO PUMPING UNIT. NU FLOW LINE TO WH. PUT WELL ON PUMP TEST @ 17:30 5-18-01. 5-23-01: RU SU. PULL PUMP. 5-24-01: PUMP STUCK. PULL FREE. RESET TAC. TIH W/PMP & RDS. 5-25-01: RIG DOWN.
5-30-01: ON 24 HR OPT. PUMPING 74 BO, 29 BW, & 22 MCF. FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant

DATE 11/12/01

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 915-688-4752

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL IF ANY: TITLE

DATE JAN 24 2002

DeSoto/Nichols 12-93 ver 1.0