

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-30970

5. Indicate Type of Lease

STATE ☒

FEE

6. State Oil / Gas Lease No.

B-1056-1

7. Lease Name or Unit Agreement Name

VACUUM GLORIETA WEST UNIT

8. Well No.

48

9. Pool Name or Wildcat

VACUUM GLORIETA

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well: OIL WELL ☒ GAS WELL OTHER

2. Name of Operator

TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator

205 E. Bender, HOBBS, NM 88240

4. Well Location

Unit Letter P : 815 Feet From The SOUTH Line and 800 Feet From The EAST Line

Section 25

Township 17S

Range 34E

NMPM

LEA COUNTY

10. Elevation (Show whether DF, RKB, RT,GR, etc.)

3990' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK

PLUG AND ABANDON

REMEDIAL WORK ☒

ALTERING CASING

TEMPORARILY ABANDON

CHANGE PLANS

COMMENCE DRILLING OPERATION

PLUG AND ABANDONMENT

PULL OR ALTER CASING

CASING TEST AND CEMENT JOB

OTHER

OTHER:

SQZ LOWER/PERF STIM UPPER GLORIETA ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-21-00: MIRU. NDWH. NUBOP. UNLOAD, RACK, TALLY WS. TIH W/BIT, CSG SCRAPER, WS. TAG UP @ 5919'. CIRC W/10# BRINE. TEST CSG & CIBP TO 500 -PSI. LEAK OFF. TIH W/PKR, SN, WS TO 1643'.

3-22-00: TIH W/TBG TO 5888'. SET PKR. TEST CIBP @ 5919'. TO 500 PSI-OK. MOVE PKR & LOOK FOR LEAK. TEST FR 4500-SURF. DV TOOL @ 4681'.

3-23-00: LEAK FR 4942-5039'. SET PKR @ 4942'. RU SWAB. REL PKR.

3-24-00: TIH OPEN ENDED W/TBG TO 5089'. CIRC CSG W/FW. BATCH MIX 30 SX CMT, & SPOT 5089-4795.

3-27-00: TIH W/BIT, DC'S & TBG, TAG @ 4835'. DRILL CMT TO 5125'. FELL OUT CMT. TEST CSG TO 500 PSI-30 MIN. TIH TO 5919'. TAG CIBP.

3-28-00: DISPL CSG W/10# BRINE. DRILL CIBP @ 5919'. RUN BIT TO 6296'. CIRC CLN. BIT SWING @ 5898'.

3-29-00: TIH W/PKR, SN, TBG. SET PKR @ 5918'. REL PKR. TIH W/RET, TBG. PUMP THRU RET. SET @ 5918'. TEST TBG TO 2000 PSI-OK.

3-30-00: PSI CSG TO 500-OK. PUMP 50 SX CL C & 100 SX CL C NEAT. FLSH W/33 BBLS. TIH W/BIT, DC'S & TBG TO 3130'.

3-31-00: TIH TO 5915'. DRILL 2' CMT, CMT RET @ 5917'. CMT TO 5990'.

4-03-00: DRILL CMT 5990-6000'. TIH W/PERF GUN & PERF 5876-5950, 5953-58, 5954-86. TIH W/PKR, SN, TBG. SET PKR @ 5820'. LOAD/TEST CSG TO 500 PSI-OK.

4-04-00: PSI CSG TO 500-OK. ACIDIZE GLORIETA PERFS 5876-5986 W/7000 GALS 15% NEFE HCL ACID. RU SWAB. FL @ SURF. END FL @ 1700'.

4-05-00: FL @ 1500'. END FL @ 5500'.

4-06-00: FL @ 2200'. END FL @ 4900'. REL PKR. TIH & TAG @ 6000'. NO FILL. TIH W/PERF SUB, SN, BLAST JT, TBG, TAC. NDBOP. SET TAC. NUWH. SN @ 5993'. TAC @ 5756'.

4-07-00: UNLOAD RDS. TIH W/NIP, PUMP, RDS. LOAD/TEST/CHECK PUMP ACTION-OK. RIG DOWN.

4-16-00: ON 24 HR OPT. PUMPED 23 BO, 20 BW, & 17 MCF. PERFS 5876-5986 VACUUM GLORIETA.

FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

J. Denise Leake

TITLE

Engineering Assistant

DATE 5/8/00

TYPE OR PRINT NAME

J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL IF ANY:

TITLE

DATE