

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30 025 30985
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V 1357

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name Mitchell 16 State	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		8. Well No. 3	
2. Name of Operator Meridian Oil Inc.		9. Pool name or Wildcat North Young (San Andres)	
3. Address of Operator P.O. Box 51810, Midland, TX 79710-1810			
4. Well Location Unit Letter G : 1650 Feet From The North Line and 2310 Feet From The East Line Section 16 Township 18S Range 32E NMPM Lea County			
		10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3787' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: Temporarily Abandon <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU. POH w/rods and pump. Install BOPE. POH w/2 7/8" tubing.
RIH w/2 7/8" tubing, bit and scraper to 4780'. Spot 15 bbls 10ppg gelled brine.
RIH w/ dump bailer and cap CIBP @ 4780' w/ 35' Class C cement.
RIH w/5 1/2" 17# CIBP on wireline and set @ 4525'. Cap w/ 35' Class C cement. Test casing to 500 psi.
RIH w/ 2-7/8" tubing to 4450'. Circulate hole with inhibited packer fluid.
POH w/tubing. Lay down same. RIH w/1 jt. 2 7/8" tubing and place valve atop same.
Restore location as directed.

THE COMMISSION MUST BE NOTIFIED
24 HOURS PRIOR TO COMMENCING WORK

**Future SWD candidate.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Production Asst. DATE 8/17/93
TYPE OR PRINT NAME _____ TELEPHONE NO. _____

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE AUG 20 1993

CONDITIONS OF APPROVAL, IF ANY: