

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CONTACT RECEIVING
OFFICE FOR NUM
OF COPIES REQUIRED
(Other instructions on re-
verse side)

BLM Roswell District
Modified Form No.
NMX60-3160-4

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		3. AREA CODE & PHONE NO. 505-746-9811		5. LEASE DESIGNATION AND SERIAL NO. NM 36915	
2. NAME OF OPERATOR JFG ENTERPRISE		6. IF INDIAN, ALLOTTEE OR TRIBE NAME		7. UNIT AGREEMENT NAME	
3. ADDRESS OF OPERATOR P.O. Box 100, Artesia, New Mex		8. FARM OR LEASE NAME Lowell Fred		9. WELL NO. 1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface K		10. FIELD AND POOL, OR WILDCAT Tonto Bone Springs		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 15-T-19S-R-33E	
14. PERMIT NO. 30-025-31008		15. ELEVATIONS (Show whether DF, RT, OR, etc.) 3641.7 KB - 3622.7 GR		12. COUNTY OR PARISH LEA	
				18. STATE New Mex	

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)

PULL OR ALTER CASING
MULTIPLE COMPLETE
ABANDON*
CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other)

REPAIRING WELL
ALTERING CASING
ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)
- 5-9-91: Moved IN P.V. R1990 UP B.O.P. Come out of hole WITH 2 7/8" Tubing. Tested wellhead + B.O.P. To 3000 PSI.
- 5-10-91 PERF 2 SPF - (9440-9448) 16 Holes. Acidize w/ 1500 15% NE FE. Form. Back @ 4180 PSI. Pump: 2.8 BPM. @ 3800 PSI. ISIP 3100* 15 min Shut in 2693*. TOTAL Load to Recover 100 Bbls. Open well up IN 30 min. Flowed BACK 20 min + STARTED SWABBING. SWAB BACK 2 1/2 DAYS. NO PRESSURE BUILD UP. WATER 99% OIL 1%.
- 5-13-91. SWAB 3 HRS. NO CHANGE IN FLUID. Come out of hole. SET BRIDGE PLUG AT 9296 FT. PERF 9156-9171 FT. 38 holes. ON 5-14-91 ACIDIZE w/ 2500 GAL 15% NE FE. : AVG TAT PSI 3170*. ISIP-2380* 15 min S.I.P. 2150*. 59.5 Bbls ACID. 59.2 bbls. Flush. Flowed BACK 5 min. SWAB REST OF DAY. Recovered 75 bbls FLUID. LAST HR HAD A 10% OIL CUT. SWAB ALL DAY ON 5-15-91. FROM NOON UNTIL 6:00 P.M. OIL CUT WAS 50% OIL - 50% WATER. WILL FRAC.
- 5-16-91. FRAC w/ 48391 GAL OF 40" GEL FLUID. 520 SX 20/40 OTTAWA SAND. 140 SX 16/30 OTTAWA SAND. AVG TATG PSI. 3573* AVG RATE 30.1 BPM. I.S.I.P. 3237* 15 min SIP 3057*. SWAB 4 DAYS: Recovered 675 Bbls TREATING WATER 130 Bbls OIL. RIGGING UP PUMPING UNIT + TANK BTAY.

I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Partner

DATE FOR RECORD

6-5-91

(This space for Federal or State office use)

APPROVED BY

TITLE

AR

DATE

CONDITIONS OF APPROVAL, IF ANY:

OSAD, NEW MEXICO

RECEIVED

JUN 23 1961

HC.