## State of New Mexico

Form C-100

E. gy, Minerals and Natural Resources Department Revised 1-1-49 District Office DISTRICT I OIL CONSERVATION DIVISION WELL API NO. P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088 30-025-31190 Santa Fe. New Mexico 87504-2088 P.O. Drawer DD, Artesia, NM 88210 5. Indicate Type of Lease FEE 🗵 STATE 1000 Rio Brazos Rd., Aztec, NM 87410 6. State Oil & Gas Lease No. SUNDRY NOTICES AND REPORTS ON WELLS ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) Type of Well: AMET XX 201 PF. JA 1 OTHER 2. Name of Operator PHILLIPS PETROLEUM COMPANY 3. Address of Operator 9. Pool same or Wildox 4001 PENBROOK ST. ODESSA, TX 79762 Iovington (Paddock) Well Location 1830 North 660 West Unit Letter \_ \_ Feet From The Line and Foot From The Line 37-E 17-S Lea makip 1/-5 Range 3/-E

10. Elevation (Show whether DF, RKB, RT, GR, etc.) Section Town thip GL 3806.81; LKB 3818.81 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK **ALTERING CASING** TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP NS. PLUG AND ABANDONMENT **PULL OR ALTER CASING** CASING TEST AND CEMENT JOB Perforate and acidize OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 7/28/91 MI & RU DDU. GIH w/4-1/2" bit, drill out cement & DV tool @ 4051. Drill past float collar @ 6256' to TD of 6302'. Ran GR-CCL-log from 6298'-2300'. Ran 4" casing gun & perforated 16' @ 6250'-6266', 7/29/91 8/1/91 Acidize perforations 6250'-6266' w/1300 gal. 20% NeFe HCL. 8/3=5/91 Swabbing load. Acidize perforations 6250'-6266' w/2000 gal. 20% HCL 8/6/91 8/7/91 Swabbing load. + set Q 6191, 8/9/91 GIH w/5-1/2" 15.5# EZSV retainer/& sqzd. 25 sacks Class C cement below retainer. Dump 5 sacks on top of EZSV retainer. 8/10/91 Perforate 5414'-5428', 14', 14 shots (4" casing gun - 1 SPF). Set packer @ 5365'. Treat perforations 5414'-5428' w/1200 gal. 20% acid. 8/11/91 8/12/91 Swabbing Load. Perforațe 5070'-5078' (8'); 5082'-5094' (12'); 5097'-5110' (13'); 5115'-5132' (17') 8/13/91 Over 9/20/91 www. Supervisor, Regulation & Proration **(915)** 368-1667 HANT HANG

RICINAL SIGNED BY JERRY SEXTOM

DISTRICT LISUPERVISOR

CONDITIONS OF APPROVAL, S' ANY:

APPROVED BY

Der amended C 103 dated 9-20-91

調整とと同門

8/13/91 Total of 50' & 50 shots. (4" casing gun, 1 SPF). Set packer @ 5000'. Treat (contd.) perforations 50' -5132' w/4250 gal. 20% acid.

8/14-18/91 Swabbing load.

8/19/91 GIH w/retainer & set @ 5015'. Sqzd. 100 sack cement into perforations 5070'-5132'.

ا در اورون در اورون

8/20-21/91 Drill out retainer & cement.

8/24/91 Fracture treat perforations 5414'-5428' w/18000 gal. gelled x-linked water carrying 49000# 20/40 mesh sand.

9/11/91 Pumped 46 BO & 164 BW.

TEMP. DROP PENDING POTENTIAL TEST.

ASCSIVED

. Horiz VI

SEP 23 1931