Form 3160-5

UN 'ED STATES

SUBMIT IN TRIP' ATE'

rorm approved. Budget Bureau No. 1004-0135 Expires August 31, 1985

Pormerly 9-331)	DEPARTME OF THE !NTER BUREAU OF LAND MANAGEMEN	5. LEASE DESIGNATION AND SERIAL NO. NM 53239					
SUN (Do not use thi	NDRY NOTICES AND REPORTS ts form for proposais to drill or to deepen or plug Use "APPLICATION FOR PERMIT—" for such	ON WELLS back to a different reservoir. proposais.)	d. IF INDIAN, ALLOTTEE	GR TRIBE NAME			
OIL GAS WELL WELL		7. UNIT AGREEMENT NAME					
2. NAME OF OPERATOR	— Diy-noic	S. FARM OR LEASE NAME					
Enron Oil &	Gas Company	Bingo Federal 9. WELL NO.					
P. O. Box 2	267, Midland, Texas 79702 Report location clearly and in accordance with an		1				
See also space 17 be	(Report location clearly and in accordance with an elow.)	10. FIELD AND POOL, OR WILDCAT					
At aurtace			Corbin, West Delaware				
2310' F	FSL & 1980' FEL		11. SEC., T., B., M., OR BLE. AND SURVEY OR AREA				
			Sec. 13, T18S, R32E				
30 025 3119	15. BLEVATIONS (Show whether to 3833.3)		12. COUNTY OF PARISH 13. STATE				
TEST WATER SHUT-FRACTURE TREAT SHOOT OF ACIDIZE	MULTIPLE COMPLETE ABANDON*	SUBSECTION OF STREET	QUENT REPORT OF: REPAIRING W ALTERING CAS ABANDONMENT	BING			
REPAIR WELL (Other)	CHANGE PLANS	(Other) (Noun: Report resultant or Recommendation or Recommendation or Recommendation or Recommendation)	ts of multiple completion o	n Well			
17. DESCRIBE PROPOSED of proposed work, nent to this work.	OR COMPLETED OPERATIONS (Clearly state all pertian If well is directionally drilled, give subsurface loc.).	ent details, and give pertinent date eations and measured and true verti	s, including estimated date cal depths for all markers	of starting any and zones perti-			
TD 5350'.							
	set cmt plug from 4606' to 45 14.8 ppg.	06' w/42 sx prem plus	neat cmt, 1.32	cuft/sx,			
	set cmt plug 2690' to 2490' w	/120 sx prem plus nea	t w/1.32 cuft/sx	, 14.8 ppg.			
	set cmt plug 1400' to 1250' w 1.48 ppg.	/7 \$ sx prem plus neat	cmt + 2% CaCl w	/1.32 cuft/s			

04-01-91 - tagged cmt @ 1184'.

1.

set cmt plug 456' to surface w/125 sx prem plus neat cmt w 1.32 cuft/sx, 14.8 ppg.

Jet & clean mud pits & install dry-hole marker; released rig @ 11:00 am (MST) 04-01-91.

•				_		456'	and	circulate No cas	ed to	surface ecovered	w/275	sx	Hallib	C1	C
creby cur	tify that the	forego n	is true and	correct	mimt r	R	egula	itory Ana	lyst	2.4		1/4/	91		

Bett Gildon This space for Federal or State office use; TITLE _ FPRROVED BY CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side