Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM									
	88240 C	OIL CONSERVATION DIVISION			WELL API NO.				
P.O. Box 1980, Hobbs, NM 88240  P.O. Box 2088  DISTRICT II  Santa Fe, New Mexico 87504-2088					30 025 31266				
P.O. Drawer DD, Artesia, NM 88210					5. Indi	cate Type of Lea	STATE X	F	EE 🗌
DISTRICT III 1000 Rio Brazos Rd., Azzec, NM 87410					6. State Oil & Gas Lease No.				
					B 4	120		ידדדי	77777
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)						7. Lease Name or Unit Agreement Name			
1. Type of Well:		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			Wes	st Loving	ton Uni	t	
METT	WELL	OTHER	Inj	ection					
2. Name of Operator	OT EIRC CODI	DOD ATTOM			8. Wei	ll Nc.			
GREENHILL PETROLEUM CORPORATION  3. Address of Operator						9. Pool name or Wildcat			
	ER, SUITE	200/HOUSTON, TH	EXAS 77	7077-6841	W.	Levingto	n Upper	San	Andres
4. Well Location					2390	Feat From The	. N	iorth	Line
Unit Letter	<u> </u>	Feet From The	East	Line and	2370	rearrom ine		01011	Line
Section 7	7	Township 17S	Ran	ge 36E	NMPM		L	ea	County
	7///////	7///		F, RKB, RT, GR, etc.)					
		39030		Taking of NT-sine T	) and	or Other D	////////	<u> </u>	
II.	_	propriate Box to In	cicate N			JENT REF		<b>F</b> .	
NOTIC	EOFINIE	NTION TO:		301	ששפפ		OITI O		_
PERFORM REMEDIAL WO	RK 📙	PLUG AND ABANDON	• 📙	REMEDIAL WORK		ALT	TERING CA	SING	
TEMPORARILY ABANDON	· _	CHANGE PLANS		COMMENCE DRILLIN	IG OPNS.	PLU	JG AND AB	ANDON	MENT
PULL OR ALTER CASING		ASING TEST AND CEMENT JOB 🔲							
OTHER:	OTHER: Injection Conversion								
12. Describe Proposed or Co work) SEE RULE 1103.									00#.
Set AD-1 Pack	er at 4662	. 011 001 0		iio tubing.	110000			נט או	
		es. Ending pres			11000	•		נס אי	
						•		LO 31	
Ran chart for	30 minute	es. Ending pres	sure w	as 500#.		•			
Ran chart for	30 minute	es. Ending pres	sure w	as 500#.					92
Ran chart for	30 minute	es. Ending pres	sure w	as 500#.				6-11-	
Ran chart for  I hereby certify that the information of the second certification	mion above is true so	es. Ending pres	sure w	as 500#.			DATE	6-11-	
Ran chart for  I hereby certify that the infompt  SIGNATURE  TYPE OR PRINT NAME	30 minute	es. Ending pres	sure w	as 500#.			DATE	6-11-	

WFX 622