Submit 3 Copies о Арргорліаle	State of New Energy, Minerals and Natural			Form C-103 Revised 1-1-89
o Appropriate District Office <u>DISTRICT I</u> P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVAT		WELL API NO. 30-0	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	P.O. Box 2 Santa Fe, New Mexic		5. Indicate Type of La	-
DISTRICT III 1000 Rio Urazos Rd., Aziec, NM 87410			6. State Oil & Gas Le	
	LICES AND REPORTS ON W	/FILS		
(DO NOT USE THIS FORM FOR PF DIFFERENT RESE	ROPOSALS TO DRILL OR TO DEEP ROVOR. USE "APPLICATION FOR C-101) FOR SUCH PROPOSALS.)	EN OR PLUG BACK TO A	7. Lease Name or Un	-
I. Type of Well: OIL OAS WELL XX WELL			West Lovi	ngton Unit
2. Name of Operator GREENHILL PETROLEUM			8. Well No. 83	
3. Address of Operator			9. Pool name or Wild	
	ite 200, Houston, Texa			on Upper San And
Unit Letter 2,	525 South	Line and	25 Feet From Th	East L
5	17 South	36 East	NMPM Le	
Section	Township 10. Elevation (Show when	Range ther DF, RKB, RT, GR, etc.)		
			Parant or Other I	//////////////////////////////////////
		te Nature of NORCE 1	Report of Other L	Jala
	Appropriate Box to Indica		BSEQUENT RE	PORT OF:
NOTICE OF IN	ITENTION TO:	SU	BSEQUENT RE	PORT OF:
	ITENTION TO: PLUG AND ABANDON	SU REMEDIAL WORK		PORT OF:
	ITENTION TO:	SUI	BSEQUENT RE	PORT OF:
NOTICE OF IN PERFORM REMEDIAL WORK	ITENTION TO: PLUG AND ABANDON CHANGE PLANS	SUI REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND C	BSEQUENT RE	PORT OF: LTERING CASING LUG AND ABANDONMENT
NOTICE OF IN PERFORM REMEDIAL WORK	ITENTION TO: PLUG AND ABANDON [CHANGE PLANS [SUI REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND C OTHER:	BSEQUENT RE	PORT OF: LTERING CASING LUG AND ABANDONMENT
NOTICE OF IN PERFORM REMEDIAL WORK	ITENTION TO: PLUG AND ABANDON CHANGE PLANS	SU REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND C OTHER: Is, and give pertinent dates, inc	BSEQUENT RE	PORT OF: LTERING CASING LUG AND ABANDONMENT LUG AND ABANDONMENT
NOTICE OF IN PERFORM REMEDIAL WORK	TENTION TO: PLUG AND ABANDON CHANGE PLANS change plans (Clearly state all pertinent detail 92. Ran 43 joints of cement. Circulate t	SU REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND C OTHER: Is, and give pertinent dates, inc 8-5/8" 24# casin	BSEQUENT RE	PORT OF: LTERING CASING LUG AND ABANDONMENT LUG AND ABANDONMENT Maring any proposed ,820 feet with
NOTICE OF IN PERFORM REMEDIAL WORK	TENTION TO: PLUG AND ABANDON CHANGE PLANS CHANGE PLANS Crations (Clearly state all periment details 92. Ran 43 joints of Cement. Circulate to leld OK.	SU REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND C OTHER: Is, and give pertinent dates, inc 8-5/8" 24# casing to surface. Wait	BSEQUENT RE	PORT OF: LTERING CASING LUG AND ABANDONMENT arring any proposed ,820 feet with 2 hours. Tested
NOTICE OF IN PERFORM REMEDIAL WORK	TENTION TO: PLUG AND ABANDON CHANGE PLANS change plans (Clearly state all pertinent detail 92. Ran 43 joints of cement. Circulate t	SU REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND C OTHER: Is, and give pertiment dates, inc 8-5/8" 24# casing to surface. Waited and set at 5,230 rface. Waited on	BSEQUENT RE	PORT OF: LTERING CASING LUG AND ABANDONMENT farting any proposed ,820 feet with 2 hours. Tested 50 sacks of
NOTICE OF IN PERFORM REMEDIAL WORK	TENTION TO: PLUG AND ABANDON CHANGE PLANS CHANGE PLANS	SU REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND C OTHER: Is, and give pertiment dates, inc 8-5/8" 24# casing to surface. Waited and set at 5,230 rface. Waited on	BSEQUENT RE	PORT OF: LTERING CASING LUG AND ABANDONMENT farting any proposed ,820 feet with 2 hours. Tested 50 sacks of
NOTICE OF IN PERFORM REMEDIAL WORK	TENTION TO: PLUG AND ABANDON CHANGE PLANS CHANGE PLANS	SU REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND C OTHER: b, and give pertiment dates, inc 8-5/8" 24# casing to surface. Waited and set at 5,230 rface. Waited on al depth 5,230 fe	BSEQUENT RE	PORT OF: LTERING CASING LUG AND ABANDONMENT farting any proposed ,820 feet with 2 hours. Tested 50 sacks of
NOTICE OF IN PERFORM REMEDIAL WORK	TENTION TO: PLUG AND ABANDON CHANGE PLANS CHANGE PLANS	SU REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND C OTHER: Is, and give pertiment dates, inc 8-5/8" 24# casing to surface. Waited and set at 5,230 rface. Waited on	BSEQUENT RE	PORT OF: LTERING CASING LUG AND ABANDONMENT farting any proposed ,820 feet with 2 hours. Tested 50 sacks of
NOTICE OF IN PERFORM REMEDIAL WORK EMPORARILY ABANDON PULL OR ALTER CASING DTHER: 12. Describe Proposed or Completed Op work) SEE RULE 1103. Spud well 03/17/ 750 sacks of Class "C casing to 800 psi. H Ran 118 joints of Class "C" cement. C: Tested casing to 2,00 I hereby certify that the information above in	TENTION TO: PLUG AND ABANDON CHANGE PLANS CHANGE PLANS	REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND C OTHER: Is, and give pertinent dates, inc 8-5/8" 24# casing to surface. Waited and set at 5,230 rface. Waited on al depth 5,230 fe	BSEQUENT RE	PORT OF: LTERING CASING LUG AND ABANDONMENT farting any proposed ,820 feet with 2 hours. Tested 50 sacks of
NOTICE OF IN PERFORM REMEDIAL WORK EMPORARILY ABANDON PULL OR ALTER CASING DTHER: 12. Describe Proposed or Completed Op work) SEE RULE 1103. Spud well 03/17/ 750 sacks of Class "C casing to 800 psi. H Ran 118 joints of Class "C" cement. C: Tested casing to 2,00 I hereby certify that the information above in SIONATURE	TENTION TO: PLUG AND ABANDON CHANGE PLANS CHANGE PLANS	SU REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND C OTHER: Is, and give pertiment dates, inc 8-5/8" 24# casing to surface. Waited and set at 5,230 rface. Waited on al depth 5,230 fe	BSEQUENT RE	PORT OF: LTERING CASING LUG AND ABANDONMENT Aarting any proposed ,820 feet with 2 hours. Tested 50 sacks of r than 24 hours.