Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

Revised 1-1-5

P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVISION	WELL API NO.
P.O. Box 2088 DISTRICT II Santa Fe, New Mexico, 87504-2088	30-025-31629
P.O. Diewer DD, Ariesia, NM 88210	5. Indicate Type of Lease STATE X FEE
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410	6. State Oil & Gas Lease No. V-3941
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name
1. Type of Well: OIL GAS WELL X WELL COTHER	Shipp, 9206 JV-P
2. Name of Operator	8. Well No.
BTA 011 Producers 3. Address of Operator	9. Pool name or Wildcat
104 S. Pecos, Midland, TX 79701	Wildcat
4. Well Location Unit Letter G : 1980 Feet From The North Line and 16.	60 Feet From The East Line
Section 22 Township 17S Range 37E	1
Section 22 Township 17S Range 37E 10. Elevation (Show whether DF, RKB, RT, GR, etc.)	NMPM Lea County
3739' GR 3751' RT	
11. Check Appropriate Box to Indicate Nature of Notice, F	eport, or Other Data
NOTICE OF INTENTION TO: SUE	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLIN	
COMMENCE PRILLIN	
PULL OR ALTER CASING CASING TEST AND C	EMENT JOB A
OTHER: OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incluwork) SEE RULE 1103.	ding estimated date of starting any proposed
70747 522 103.	
7-22-92: Depth 4500', Cmtd 8-5/8" 32# S80 J55 csg @ 4500 Cmt circ WOC 8 hrs, Set slips & cut off, Instal BOP's, Cleaned out to shoe, Tested BOP's & csg for 30 min on fresh wtr, WOC 18 hrs total, then Drlg 7-7/8" hole.	led spool & to 1500 psi
7-22-92: Depth 4500', Cmtd 8-5/8" 32# S80 J55 csg @ 4500 Cmt circ WOC 8 hrs, Set slips & cut off, Instal BOP's, Cleaned out to shoe, Tested BOP's & csg for 30 min on fresh wtr, WOC 18 hrs total, then	led spool & to 1500 psi
7-22-92: Depth 4500', Cmtd 8-5/8" 32# S80 J55 csg @ 4500 Cmt circ WOC 8 hrs, Set slips & cut off, Instable BOP's, Cleaned out to shoe, Tested BOP's & csg for 30 min on fresh wtr, WOC 18 hrs total, the Drlg 7-7/8" hole.	led spool & to 1500 psi drld shoe,
7-22-92: Depth 4500', Cmtd 8-5/8" 32# S80 J55 csg @ 4506 Cmt circ WOC 8 hrs, Set slips & cut off, Instal BOP's, Cleaned out to shoe, Tested BOP's & csg for 30 min on fresh wtr, WOC 18 hrs total, then Drlg 7-7/8" hole. 7-24-92: Depth 5100', Drlg 7-7/8" hole. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIONATURE AND THE Regulatory Actions the set of the best of my knowledge and belief.	led spool & to 1500 psi a drld shoe, dministrator pare 7-24-92 91-5682-3753

CONDITIONS OF AFFROVAL, IF ANY: