Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-163

Revised 1-1-89

NOV 1 2'92

FO. Dest 2008 P.O. Dex 200	District Office				_
STATE PER	DISTRICT I P.O. Box 1980, Hobbs, NM 88240 DISTRICT II P.O. Drawer DD, Artesia, NM 88210 OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088			30-025-31704	
SUNDRY NOTICES AND REPORTS ON WELLS CONSTRUCT NOTICES AND RECORD					
(DO NOT USE THIS FOORM FOR PROPAGALS TO DELEGA TO THE CONTROL OF T	DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410				77
Office Completed Operation and Production Inc. 2. Name of Operator TEXACO EXPLORATION AND PRODUCTION INC. 3. Address of Operator P. O. Box 3109 Midland, Texas 79702 Midland	(DO NOT USE THIS FORM FOR PF DIFFERENT RESI (FORM	ROPOSALS TO DRILL OH TO DEEP ROVOR. USE "APPLICATION FOR	EM ON LEGG BUOK 10 V		
Name of Operator TEXACO EXPLORATION AND PRODUCTION INC. 1. Mathres of Operator P. O. Box 3109 Midland, Texas 79702 9, Pool sease or Wildow P. O. Box 3109 Midland, Texas 79702 10, Pool sease or Wildow Unit Letter E: 1484 Feet From The NORTH Line and 204 Feet From The WEST Line Section 36 Township 17-SOUTH Range 34-EAST NMPM LEA County GR-4008', KB-4022' 10. Evertice (Know whither DF, REB, RT, GR, etc.) GR-4008', KB-4022' 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 12. NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS CASHNG CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT TEMPORAFILLY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT TEMPORAFILLY ABANDON SEE RULE 1103. 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent datas, including entimated data of starting any proposed worth) SEE RULE 1103. 1. MIRU COMPLETION UNIT. CLEAN OUT CASING TO PBTD OF 6170'. TESTED CASING TO 3000 FOR 30 MINUTES 11-04- 22. 13. DOWNELL ACIDIZED WITH 6000 GAL 15% NEFE. 11-05-92. 14. TITH WITH 2 3/8 TUBING AND PACKER, SET PACKER 6 5858'. 15. TESTED PACKER TO 5009 FOR 30 MINUTES 11-07-92. 10. DOWNELL ACIDIZED WITH 6000 GAL 15% NEFE. 11-05-92. 11. DOWNELL ACIDIZED WITH 6000 GAL 15% NEFE. 11-05-92. 12. PRIPE FOR INJECTION. 11. DIRECTION. 11. DIRECTION. 12. PRIPE FOR INJECTION. 13. DOWNELL ACIDIZED WITH 6000 GAL 15% NEFE. 11-05-92. 14. TITH WITH 2 3/8 TUBING AND PACKER TO 5009 FOR 30 MINUTES 11-07-92. 15. TESTED PACKER TO 5009 FOR 30 MINUTES 11-07-92. 16. PREP FOR INJECTION. 16. PREP FOR INJECTION. 17. TILEPHONE NO. 915-6884	A	☐ OTHER WATE	R INJECTION		_
1. MIRL COMPLETION UNIT. CLEAN OUT CASING TO PSID OF 6170'. TESTED CASING TO 3000# FOR 30 MINUTES 11-04-32. 1. MINUTED RANGES AND PACKER TO SOOM FOR 30 MINUTES 11-07-92. 1. Dereby foretfy that the information above is true and complete to the best of my knowledge and balid. 1. Dereby foretfy that the information above is true and complete to the best of my knowledge and balid. 1. Dereby foretfy that the information above is true and complete to the best of my knowledge and balid. 1. Deribly foretfy that the information above is true and complete to the best of my knowledge and balid. 1. TILLE DERILLING OPERATIONS MANAGER DATE 11-09-92. 1. DERILLING OPERATIONS MANAGER DATE 11-09-92.	WELL WELL L			64	
4. Well Lossion 14. Well Lossion 15. Exercises 16. Exercises 16. Exercises 17. South 10. Exercises (Show whether DP, RKB, RT, GR, etc.) 10. Exercise (Show whether DP, RKB, RT, GR, etc.) 10. Exercise (Show whether DP, RKB, RT, GR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: ALTERING CASING OTHER: OTHE	a Address of Operator				- }
Usik Letter E : 1484 Peet Prom The NORTH Lise and 204 Peet Prom The WEST WEST TOWNSHIP 17-SOUTH Range 34-EAST NMPM LEA County 10 Devision (Show whether DP, RKB, RT, GR, etc.) 10 Devision (Show whether DP, RKB, RT, GR, etc.) 10 Devision (Show whether DP, RKB, RT, GR, etc.) 10 Devision (Show whether DP, RKB, RT, GR, etc.) 11 Devision (Show whether DP, RKB, RT, GR, etc.) 12 Devision (Show whether DP, RKB, RT, GR, etc.) 13 Devision (Show whether DP, RKB, RT, GR, etc.) 14 Devision (Show whether DP, RKB, RT, GR, etc.) 15 Devision (Show whether DP, RKB, RT, GR, etc.) 16 Devision (Show whether DP, RKB, RT, GR, etc.) 16 Devision (Show whether DP, RKB, RT, GR, etc.) 16 Devision (Show whether DP, RKB, RT, GR, etc.) 16 Devision (Show whether DP, RKB, RT, GR, etc.) 16 Devision (Show whether DP, RKB, RT, GR, etc.) 17 Devision (Show whether DP, RKB, RT, GR, etc.) 17 Devision (Show whether DP, RKB, RT, GR, etc.) 17 Devision (Show whether DP, RKB, RT, GR, etc.) 17 Devision (Show whether DP, RKB, RT, GR, etc.) 17 Devision (Show whether DP, RKB, RT, GR, etc.) 17 Devision (Show whether DP, RKB, RT, GR, etc.) 18 Devision (Show whether DP, RKB, RT, GR, etc.) 18 Devision (Show Whether DP, RKB, RT, GR, etc.) 18 Devision (Show Whether DP, RKB, RT, GR, etc.) 18 Devision (Show Whether DP, RKB, RT, GR, etc.) 18 Devision (Show Whether DP, RKB, RT, GR, etc.) 18 Devision (Show Whether DP, RKB, RT, GR, etc.) 18 Devision (Show Whether DP, RKB, RT, GR, etc.) 18 Devision (Show Whether DP, RKB, RT, GR, etc.) 18 Devision (Show Whether DP, RKB, RT, GR, etc.) 18 Devision (Show Whether DP, RKB, RT, GR, etc.) 18 Devision (Show Whether DP, RKB, RT, GR, etc.) 18 Devision (Show Whether DP, RKB, RT, GR, etc.) 18 Devision (Show Whether DP, RKB, RT, GR, etc.) 18 Devision (Show Whether DP, RKB, RT, GR, etc.) 18 Devision (Show Whether DP, RKB, RT, GR, etc.) 18 Devision (Show Whether DP, RKB, RT, GR, etc.) 18 Devision (Show Whether DP, RKB, RT, GR, etc.) 18 Devision (Show Whether DP,	P. O. Box 3109 M	idland, Texas 79702		VACUUM GLORIETA	-1
10. Elevision (Show whether DP, RKB, RT, GR, etc.) 10. Elevision (Show whether DP, RKB, RT, GR, etc.) 10. Elevision (Show whether DP, RKB, RT, GR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEMPORARILY ABANDON CHANGE PLANS OTHER: OTHER: OTHER: COMPLETION OTHER: COMPLETION OTHER: COMPLETION UNIT. CLEAN OUT CASING TO PBTD OF 6170'. TESTED CASING TO 3000# FOR 30 MINUTES 11-04-92. 2. HALLIBURTON RAN GR—CCL. PERFED WITH 2 JSPF: 5951-78, 6074-6109. 124 HOLES. 3. DOWELL ACIDIZED WITH 6000 GAL 15% NEFE. 11-05-92. 4. TIH WITH 2 3/8 TUBING AND PACKER, SET PACKER @ 5858'. 5. TESTED PACKER TO 500# FOR 30 MINUTES 11-07-92. 6. PREP FOR INJECTION.		484 Feet From The NORTH	Line and	204 Feet Proma The WEST Li	
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK	Section 36	Township 17-SOUTH 10. Elevation (Show whe	ther DF, RKB, RT, GR, etc.) 222	NAPA LEA	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS PLUG AND ABANDON PLUG AND ABANDON PLUG AND ABANDON PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB PLUG AND ABANDONMENT THE Proposed or Completed Operations (Clearly state all pertinent datalle, and give pertinent datas, including estimated data of starting any proposed work) SEE RULE 1103. 1. MIRU COMPLETION UNIT. CLEAN OUT CASING TO PBTD OF 6170'. TESTED CASING TO 3000 FOR 30 MINUTES 11-04-92. 2. HALLIBURTON RAN GR-CCL. PERFED WITH 2 JSPF: 5951-78, 6074-6109. 124 HOLES. 3. DOWELL ACIDIZED WITH 6000 GAL 15% NIEFE. 11-05-92. 4. TIH WITH 2 3/8 TUBING AND PACKER. SET PACKER @ 5858'. 5. TESTED PACKER TO 500 FOR 30 MINUTES 11-07-92. 6. PREP FOR INJECTION. Thereby bertify that the information above is true and complete to the best of my knowledge and boild. SOUND THE POINT OF		Annopriate Box to Indica	ate Nature of Notice,	Report, or Other Data	
PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: COMPLETION OTHER: COMPLETION COMPLETION COMPLETION COMPLETION COMPLETION COMPLETION COMPLETION COMPLETION COMPLETION UNIT. CLEAN OUT CASING TO PBTD OF 6170'. TESTED CASING TO 3000# FOR 30 MINUTES 11–04–92. 1. MIRU COMPLETION UNIT. CLEAN OUT CASING TO PBTD OF 6170'. TESTED CASING TO 3000# FOR 30 MINUTES 11–04–92. 2. HALLIBURTON RAN GR—CCL. PERFED WITH 2 JSPF: 5951–78, 6074–6109. 124 HOLES. 3. DOWELL ACIDIZED WITH 6000 GAL 15% NEFE. 11–05–92. 4. TIH WITH 2 3/8 TUBING AND PACKER. SET PACKER @ 5858'. 5. TESTED PACKER TO 500# FOR 30 MINUTES 11–07–92. 6. PREP FOR INJECTION. TILE DRILLING OPERATIONS MANAGER DATE 11–09–92 TILE DRILLING OPERATIONS MANAGER DATE 11–09–92 TILE DRILLING OPERATIONS MANAGER DATE 11–09–92	II. Chec.	K Appropriate Dox to marce	l SU	BSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING OTHER: COMPLETION OTHER: COMPLETION OTHER: COMPLETION 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1. MIRU COMPLETION UNIT. CLEAN OUT CASING TO PBTD OF 6170'. TESTED CASING TO 3000# FOR 30 MINUTES 11-04-92. 2. HALLIBURTON RAN GR-CCL. PERFED WITH 2 JSPF: 5951-78, 6074-6109. 124 HOLES. 3. DOWELL ACIDIZED WITH 6000 GAL 15% NIFFE. 11-05-92. 4. TIH WITH 2 3/8 TUBING AND PACKER, SET PACKER @ 5858'. 5. TESTED PACKER TO 500# FOR 30 MINUTES 11-07-92. 6. PREP FOR INJECTION. TITLE DRILLING OPERATIONS MANAGER DATE 11-09-92 TITLE DRILLING OPERATIONS MANAGER DATE 11-09-92 TITLE DRILLING OPERATIONS MANAGER DATE 11-09-92	NOTICE OF I			AI TERING CASING	
TEMPORARILY ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB OTHER: COMPLETION OTHER: COMPLETION OTHER: COMPLETION (X) SEE RULE 1103. 1. MIRU COMPLETION UNIT. CLEAN OUT CASING TO PBTD OF 6170'. TESTED CASING TO 3000# FOR 30 MINUTES 11–04–92. 2. HALLIBURTON RAN GR-CCL. PERFED WITH 2 JSPF: 5951–78, 6074–6109. 124 HOLES. 3. DOWELL ACIDIZED WITH 6000 GAL 15% NEFE. 11–05–92. 4. TIH WITH 2 3/8 TUBING AND PACKER. SET PACKER @ 5858'. 5. TESTED PACKER TO 500# FOR 30 MINUTES 11–07–92. 6. PREP FOR INJECTION. Thereby certify that the information above is true and complete to the best of my knowledge and belief. TITLE DRILLING OPERATIONS MANAGER DATE 11–09–92 TITLE DRILLING OPERATIONS MANAGER DATE 11–09–92 TITLE DRILLING OPERATIONS MANAGER DATE 11–09–92	PERFORM REMEDIAL WORK	PLUG AND ABANDON L	_		
OTHER: OTHER: OTHER: COMPLETION OF COMPLETIO	TEMPORARILY ABANDON	CHANGE PLANS	j		u
OTHER: OTHER: COMPLETION 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1. MIRU COMPLETION UNIT. CLEAN OUT CASING TO PBTD OF 6170'. TESTED CASING TO 3000# FOR 30 MINUTES 11–04–92. 2. HALLIBURTON RAN GR-CCL. PERFED WITH 2 JSPF: 5951–78, 6074–6109. 124 HOLES. 3. DOWELL ACIDIZED WITH 6000 GAL 15% NIFFE. 11–05–92. 4. TIH WITH 2 3/8 TUBING AND PACKER. SET PACKER @ 5858'. 5. TESTED PACKER TO 500# FOR 30 MINUTES 11–07–92. 6. PREP FOR INJECTION. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIONATURE C. P. Basham (SW th. TILLE DRILLING OPERATIONS MANAGER DATE 11–09–92 TELEPHONE NO. 915–6884	PULL OR ALTER CASING		İ		∇
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1. MIRU COMPLETION UNIT. CLEAN OUT CASING TO PBTD OF 6170'. TESTED CASING TO 3000# FOR 30 MINUTES 11-04-92. 2. HALLIBURTON RAN GR-CCL. PERFED WITH 2 JSPF: 5951-78, 6074-6109. 124 HOLES. 3. DOWELL ACIDIZED WITH 6000 GAL 15% NEFE. 11-05-92. 4. TIH WITH 2 3/8 TUBING AND PACKER. SET PACKER @ 5858'. 5. TESTED PACKER TO 500# FOR 30 MINUTES 11-07-92. 6. PREP FOR INJECTION. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	OTHER.		OTHER: COMPLE	TION	
1. MIRU COMPLETION UNIT. CLEAN OUT CASING TO PBTD OF 6170'. TESTED CASING TO 3000# FOR 30 MINUTES 11-04- 92. 2. HALLIBURTON RAN GR-CCL. PERFED WITH 2 JSPF: 5951-78, 6074-6109. 124 HOLES. 3. DOWELL ACIDIZED WITH 6000 GAL 15% NEFE. 11-05-92. 4. TIH WITH 2 3/8 TUBING AND PACKER. SET PACKER @ 5858'. 5. TESTED PACKER TO 500# FOR 30 MINUTES 11-07-92. 6. PREP FOR INJECTION. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE		Clarity state all portinent deta	ils, and give pertinent dates, in	cluding estimated date of starting any proposed	
92. 2. HALLIBURTON RAN GR-CCL. PERFED WITH 2 JSPF: 5951-78, 6074-6109. 124 HOLES. 3. DOWELL ACIDIZED WITH 6000 GAL 15% NIEFE. 11-05-92. 4. TH WITH 2 3/8 TUBING AND PACKER. SET PACKER @ 5858'. 5. TESTED PACKER TO 500# FOR 30 MINUTES 11-07-92. 6. PREP FOR INJECTION. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIONATURE	work) SEE RULE 1103.				
3. DOWELL ACIDIZED WITH 6000 GAL 13% NETC. 4. TH WITH 2 3/8 TUBING AND PACKER. SET PACKER @ 5858'. 5. TESTED PACKER TO 500# FOR 30 MINUTES 11-07-92. 6. PREP FOR INJECTION. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	1. MIRU COMPLETION UNIT.	CLEAN OUT CASING TO PBTD	OF 6170'. TESTED CA	ASING TO 3000# FOR 30 MINUTES 11-04	_
SIGNATURE C. P. Basham CWH TITLE DRILLING OPERATIONS MAINAGEN BATE TELEPHONE NO. 915-6884	3. DOWELL ACIDIZED WITH 4. TIH WITH 2 3/8 TUBING 5. TESTED PACKER TO 500	AND PACKER. SET PACKER @	5858'.	124 HOLES.	
SIGNATURE C. P. Basham CWH TITLE DRILLING OPERATIONS MAINAGEN BATE TELEPHONE NO. 915-6884					
SIGNATURE C. P. Basham CWH TITLE DRILLING OPERATIONS MAINAGEN BATE TELEPHONE NO. 915-6884					
SIGNATURE C. P. Basham CWH TITLE DRILLING OPERATIONS MAINAGEN BATE TELEPHONE NO. 915-6884					
SIGNATURE C. P. Basham CWH TITLE DRILLING OPERATIONS MAINAGEN BATE TELEPHONE NO. 915-6884	I hereby certify that the information above	is true and complete to the best of my knowle	odge and belief.	DATIONS MANAGER 11-09-92	
	C 2 72	sham/sw#	TITLE DRILLING OPER		8846
TYPLUS CREAT COMP.	TYPE OR PRINT NAME C. P. BASH	AM		IDARTANE IV.	

_ TILE -

APPROVED BY ---

(This space for State UnDRIGINAL SIGNED BY JERRY SEXTON

DISTRICT I SUPERVISOR