

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30 025 31875
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil / Gas Lease No.	B-155-6
7. Lease Name or Unit Agreement Name	VACUUM GLORIETA WEST UNIT
8. Well No.	108
9. Pool Name or Wildcat	VACUUM GLORIETA
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	GR-3986', KB-4000'

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☐ GAS WELL ☐ OTHER WATER INJECTION

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator
205 E. Bender, HOBBS, NM 88240

4. Well Location
Unit Letter P : 213 Feet From The South Line and 351 Feet From The EAST Line
Section 36 Township 17-SO Range 34-EA NMPM LEA COUNTY

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☒ LATERAL

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-16-98: MIRU. NUBOP. REL PKR. TOH W/TBG.
6-17-98: WRK CSG SCRAPER FR 5860-5890'. TOH W/TBG IN DERRICK. RIH W/CCL/JUNK BASKET & GAUGE RING TO 5950'. TIH W/CIPB & SET @ 5916'. TIH W/2 3/8" TBG OPEN ENDED. PSI TEST CIBP, BOPS & RAMS TO 1000 PSI-OK. TOH W/TBG.
6-18-98: TIH TO 2400'. TIH W/GYRO.
6-19-98: MILL WINDOW FR 5873-5880'. CIRC CLN. DRILLING.
6-25-98: TD @ 6445'. TIH & LD 25 JTS OF 2 7/8" TBG. TIH W/RBP. PSI TEST CSG TO 500 PSI-OK. REL RIG.
6-30-98: SET PIPE RACKS & UNLOAD 192 JTS OF 2 7/8" TBG. TIH TO 5702'.
7-01-98: CATCH BP @ 5700'. REL & EQUALIZE. TOH W/TBG. TIH W/5 JTS TBG & PKR & SN. TIH W/182 JTS TBG @ 5702'. PSA 5712'. RE-ENTRY GUIDE @ 5875'. NU TREE ON TOP OF BOP.
7-02-98: PRESS TEST LINES 3055 PSI-OK. TIH & TAG FLUID @ 920'. TIH TO 6445'. CLOSE ANNULUS. INJECT FOAM, ACID, PAD IN 4 STGS. USED 8000 GALS 15% HCL. FLOW BACK ON 14/64" CHOKE.
7-03-98: FLOW PRES OFF TBG TO TANK.
7-07-98: ND FRAC TREE. OPEN PKR BYPASS. TOH W/PKR. PU WHIPSTOCK & TIH. TIH W/33 STD KILL STRING.
7-08-98: TOH W/2 7/8" TBG, PKR SN & 187 JTS TBG. TAG PKR & WORK INTO LOWER LATERAL. PSA 5860'. END OF TBG @ 5948'. NU FRAC TREE. RDSU.
7-11-98: TIE IN PUMP TRUCKS FOR COIL TBG JOB. TIH W/1 1/2" COIL TBG TO 6590'. PULL UP COIL TBG TO 5800'.
7-12-98: TIH W/COIL TBG TO 6590'. ACIDIZE 1ST & 2ND STGS. PULL COIL TBG BACK INTO 2 7/8" TBG ABOVE SN.
7-13-98: TIH W/COIL TBG. ACID WASH. TBG PSI-2988 PSI. OPEN WELL & FLOW TO TEST TANK.
7-14-98: RU SWAB.
7-16-98: ND FRAC TREE. REL PKR. TOH & LD 2 7/8" TBG. LOAD OUT 2 7/8" TBG & REC 2 3/8" TBG.
7-18-98: BLEED TBG TO TANK. DISPL CSG W/130 BBLS PKR FLUID. PSA 5786'. NU WELL TO INJ LINE.
7-21-98: ON 24 HR OPT. INJ'G 1347 BWPD @ 1818 PSIG.
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 7/31/98
TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: _____