Submit 3 Copies to Appropriate

CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

District Office				J	Revised 1-1-89	
DISTRICT I P.O. Box 1980, Hobbs NM 88241-1980	OIL CONSERVATION	ON DIVISION				
DISTRICT II	P.O. Box 2	WELL API NO.	30-025-3	1882		
P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088			5. Indicate Type of Lease			
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6 50 60 5 5	STATE	FEE X	
	050 110 5		6. State Oil & G	is Lease No.		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A						
I DII I CHENT RESERVOIR, USE "APPLICATION FOR PERMIT"			7. Lease Name or Unit Agreement Name			
1. Type of Well:	101) FOR SUCH PROPOSALS.)	CONE Com,				
OIL GAS WELL	OTHER					
2. Name of Operator		8. Well No.				
RAND OIL & GAS, INC.	vc. 69210 258 15.			1		
3. Address of Operator 4006 BELTLINF #290 ADD	of Operator ODG BELTLINE #290 ADDISON, TX 75244			9. Pool name or Wildcat		
4. Well Location			SOUTH KNOWLE	S DEVONIAN	1364 8/1	
Unit Letter J : 1980	Feet From The S	Line and 19	80 Feet Fro	m The	E Line	
Section 12	Township 17S R	tange 38E	NIMDM	LEA		
	10. Elevation (Show wheth	her DF, RKB, RT, GR, etc	NMPM	- V///////	County	
11. Check Apr	Y/////	Notare -CN	n .	<i>X////////////////////////////////////</i>		
NOTICE OF IN	oropriate Box to Indicate	Nature of Notice,	Report, or ()ther Data	a	
	·	306	SEQUENT	REPOR	T OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON X	REMEDIAL WORK		ALTERING C	ASING	
TEMPORARILY ABANDON	CHANGE PLANS	OPNS. PLUG AND ABANDONMENT				
PULL OR ALTER CASING		CASING TEST AND CE	MENT JOB		DI MECHINENT	
OTHER:		OTHER:			_	
12. Describe Proposed or Completed Occasion	diagram (Classical Articles and Classical Art				L	
 Describe Proposed or Completed Opera work) SEE RULE 1103. 	dons (Clearly state all pertinent det	ails, and give pertinent dat	es, including estima	ited date of sta	rting any proposed	
1) CET E 1/2# CIPD 1	0.4004 0.000					
2) GIH W/ TRG & INAD	2,100' & CAP W/ 35 SXS CM	IT.				
2) GIH W/ TBG & LOAD HOLE WITH PLUGGING MUD. 3) SPOT 100' PLUG FROM 8950-9050'.						
4) CUT 5 1/2" CSG @ 7000' & PULL.						
5) SPOT 100' PLUG 50	' IN AND 50' OUT OF CSG S	TUB.				
6) SPOT 100' PLUG AT	4900-5000'.					
8) SPOT 10 SXS AT SUI	BASE OF SALT (1600-1700')					
9) CUT OFF WELLHEAD.	INSTALL REGULATION ABAN	DONMENT MARKER				
I hereby certify that the information above is true	and complete to the best of my knowledge	e and belief.				
SIGNATURE	Уде ти	LE AGENT		DATE	2/07/96	
TYPE OR PRINT NAME E. M. HODGE						
(This space for State Use)				LLEFHONE NO.	915-563-0430	
Orig. Sig Paul F		~ .				
APPROVED BY Geolo		e Geologis	Ŷ	ΔPI	R 1-8 1995	
CONDITIONS OF APPROVAL IF ANY		~		DATE	: · · • i⊍33	

THE COMMERCIAL CONTROL NOT SEEN TO SEE A SEE ASSESSMENT OF SEE ASSESSMENT OF SEE ASSESSMENT OF SECURITIES ASSESSMENT OF S