Submit 3 Copies to Appropriate District Office

CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

District Office			
DISTRICT I P.O. Pox 1980, Hobbs NM 88240	OIL CONSERVATION DIVISION		LL API NO.
P.O. Box 2088 DISTRICT II P.O. Drawer DD, Artesia, NM 88210 P.O. Drawer DD, Artesia, NM 88210		8 87504-2088	30-025-32058
		5. 1	indicate Type of Lease STATE X FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	1	6. 5	STATE LAI FEE L. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS			8-1404
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			
			case Name or Unit Agreement Name
1. Type of Well:	2-101) FOR SUCH PHOPOSALS.)		ST VACUUM GB/SA UNIT
OIL GAS WELL	OTHER	TR	ACT 2721
2. Name of Operator			Vell No.
Phillips Petroleum Com	pany	·	003
3. Address of Operator 4001 Penbrook Street,	Odessa, TX 79762		Pool name or Wildcat VACUUM GB/SA
4. Well Location Unit Letter N: 66	O Feet From The SOUTH	Line and 1415	Feet From The WEST Line
Section 27	Township 17 S Ran 10. Elevation (Show whether	rige 35 E NMP	M LEA County
	10. Lievation (Salow Whether	3935' GR	
11. Check A	ppropriate Box to Indicate l	Vature of Notice, Ren	ort, or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
DEDECORM DEMENSION IN THE PROPERTY OF THE PROP	BUILD AND 12117-11		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	LI ALTERING CASING LI
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT			S. PLUG AND ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND CEMENT	JOB 🗌
OTHER:		OTHER: ACIDIZED &	RETURNED TO PRODUCTION X
12. Describe Proposed or Completed Opwork) SEE RULE 1103.	erations (Clearly state all pertinent deta	lls, and give pertinent dates, in	chiding estimated date of starting any proposed
3/24/95 MIRU DDU. NU	BOP. COOH LD TBG & PKR	. TRIP SAND PUMP,	TAC MAGO' DII CTU WACCO
SCRAPER ON THE	TO 4335'.	. IRIP SAND PUNP,	TAG @4460'. PU GIH W/CSG
3/25/95 COOH W/SCRAPER	R. PU GIH W/TBG TAG 044	70' CLEAN OUT TO 4	705'. CIRC CLEAN. COOH. PU
GIH W/PKR AND	TBG.		• • • • • • • • • • • • • • • • • • • •
3/26/95 PUMP SCALE CON 3/27/95 COOH W/TBG. F		DC ND DAD CLAS	CE IID WELLUFAR LOAD AND TO
CSG & PKR. RI	PU GIH W/ PROD PKR AND T OMO DDU.	DG. NU BUP. FLAN	GE UP WELLHEAD. LOAD AND TEST
	15% FERCHECK ACID.		
4/06/95 TEST 24 HRS 50 BOPD 502 BWPD 467 MCF.			
I hereby certify that the information above is	true and complete to the best of my knowledge	and belief.	
SIGNATURE	Sander THE	SUPERVISOR, REG.	AFFAIRS DATE 4/12/95
TYPE OR PRINT NAMEMSANDE			TELEPHONE NO.915/368-1488
(This space for State Use)	MAL CICATED ON		
Unidi	NAL SIGNED BY IARY WINK		APR 17 1995
APPROVED BY FI	ELD REP. II		DATE
		·	VALE