Form 3160-5 (June 1990)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

N . OIL	ONS. COMMISSION
PO ROX	1980Budget Bureau Ng. 10946135

CUNT					
BUREAU OF LAND MANAGEMENT  SUNDRY NOTICES AND REPORTS ON WELLS			5. Lease Designation and Serial No. NM-11118		
	proposals to drill or to deepen or reentry to a different	ent reservoir	6. If Indian, Aliatte or Trib	Neme	
Use "APP	PLICATION FOR PERMIT—" for such proposals				
	SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement		
1. Type of Well			8910180420 BONE SPRING DESIGNATION		
X Oli Well Gas Wel	il Other		BONE SPRING DI	SIGNATION	
2. Name of Operator			8. Well Name and No.		
Harvey E. Yates Cor	mpany		YOUNG DEEP UNIT #21		
			9. API Well No. 30-025-32	1299	
3. Address and Telephone Na.					
P.O. Box 1993 , Roswell, NM 88202 1-505-623-6601			10. Field and Pool, or Exploratory Area UND. YOUNG BONE SPRING, N.		
	M Bound David Library		11. County or Parish, State		
4. Location of Well (Footage, Sec., T., R.	WL SEC. 3, T-18S, R-32E. NOTE: BOTTOM I	IOLE	LEA COUN		
	D. BOTTOM HOLE POSITION AT 10,975 WAS				
1617' FSL & 1334' F	WL SEC. 3. T-18S, R-32E		<u> </u>		
12. CHECK APPROPRIA	ATE BOX(s) TO INDICATE NATURE OF NOT	TICE, REPORT, O	R OTHER DATA		
TYPE OF SUBMISSION	N TYPE	OF ACTION			
Notice of Intent	Abandonment	Change in Pi			
	X Recompletion	New Constru			
X Subsequent Report	Plugging Beck	Non-Routine Water Shut-O	•		
	Casing Repair Aftering Casing	Conversion to			
Final Abandoment	Other	Dispose Wate	r		
		(Note: Report results	of multiple completion on Well		
		The second secon	pirtim Report and Log Form.)		
	(Clearly state all pertinent details, and give pertinent dates, including extraored date	of studing any proposed work. I	I well is directionally drilled,		
gire subswitce instinu and men	used and true vertical depths for all markers and more pertheent to this work.)				
1. 3-8-95 RU WEDGE & PERF 4 HOLES FRO	& SET CIBP @ 10,300'. DUMPED 50' CMT ON TO OM 8,761 TO 8,824' (OA) BONE SPRING.	OP. (PBTD @ 10,250	)').		
2. 3-9-95 SPOT 200 GA	LS 10% & BREAK DOWN PERFS. FOLLOW w/	3800 GALS SAME &	& BALL SEALERS.		
				op	
3. 3-14-95 FRAC BONE	E SPRING PERFS 8761-8824' (OA) w/ 65,000 GALS	S WF-30 & 118,740#	's 20-40 ECONOPRO	<b>DP</b>	
3. 3-14-95 FRAC BONE 4. 3-15-95 GIH w/ TBG	E SPRING PERFS 8761-8824' (OA) w/ 65,000 GALS	S WF-30 & 118,740#	's 20-40 ECONOPRO	op	
3. 3-14-95 FRAC BONE 4. 3-15-95 GIH w/ TBG	E SPRING PERFS 8761-8824' (OA) w/ 65,000 GALS	S WF-30 & 118,740#	's 20-40 ECONOPRO	<b>DP</b>	
3. 3-14-95 FRAC BONE 4. 3-15-95 GIH w/ TBG	E SPRING PERFS 8761-8824' (OA) w/ 65,000 GALS	S WF-30 & 118,740#	's 20-40 ECONOPRO	<b>o</b> P	
3. 3-14-95 FRAC BONE 4. 3-15-95 GIH w/ TBG	E SPRING PERFS 8761-8824' (OA) w/ 65,000 GALS	S WF-30 & 118,740#	's 20-40 ECONOPRO	<b>op</b>	
3. 3-14-95 FRAC BONE 4. 3-15-95 GIH w/ TBG	E SPRING PERFS 8761-8824' (OA) w/ 65,000 GALS	S WF-30 & 118,740#	's 20-40 ECONOPRO	<b>OP</b>	
3. 3-14-95 FRAC BONE 4. 3-15-95 GIH w/ TBG	E SPRING PERFS 8761-8824' (OA) w/ 65,000 GALS	S WF-30 & 118,740#	Is 20-40 ECONOPRO  ID BOP NU WH.		
3. 3-14-95 FRAC BONE 4. 3-15-95 GIH w/ TBG RUN PUMP & ROD	E SPRING PERFS 8761-8824' (OA) w/ 65,000 GALS, TAC AND REMAINING TBG & SN TO 8,575', SE S. PUT ON PRODUCTION.	S WF-30 & 118,740#	's 20-40 ECONOPRO		
3. 3-14-95 FRAC BONE 4. 3-15-95 GIH w/ TBG	E SPRING PERFS 8761-8824' (OA) w/ 65,000 GALS, TAC AND REMAINING TBG & SN TO 8,575', SE S. PUT ON PRODUCTION.	S WF-30 & 118,740#	Is 20-40 ECONOPRO  ID BOP NU WH.		
3. 3-14-95 FRAC BONE 4. 3-15-95 GIH w/ TBG RUN PUMP & ROD	E SPRING PERFS 8761-8824' (OA) w/ 65,000 GALS, TAC AND REMAINING TBG & SN TO 8,575', SE S. PUT ON PRODUCTION.	S WF-30 & 118,740#	Ta 20-40 ECONOPRO		
3. 3-14-95 FRAC BONE 4. 3-15-95 GIH w/ TBG RUN PUMP & ROD  14. I hereby certify that the foregoing to	E SPRING PERFS 8761-8824' (OA) w/ 65,000 GALS  TAC AND REMAINING TBG & SN TO 8,575', SE  S. PUT ON PRODUCTION.  PAY F. NOKES THE PROD. MGI	S WF-30 & 118,740#	Ts 20-40 ECONOPRO		
3. 3-14-95 FRAC BONE 4. 3-15-95 GIH w/ TBG RUN PUMP & ROD  14. I hereby certify that the directing to	E SPRING PERFS 8761-8824' (OA) w/ 65,000 GALS  TAC AND REMAINING TBG & SN TO 8,575', SE  S. PUT ON PRODUCTION.  PAY F. NOKES THE PROD. MGI	S WF-30 & 118,740#	2s 20-40 ECONOPRO  ID BOP NU WH.		
3. 3-14-95 FRAC BONE 4. 3-15-95 GIH w/ TBG RUN PUMP & ROD  14. I hereby certify that the foregoing to  Signed  (This space for Foderal or State of	E SPRING PERFS 8761-8824' (OA) w/ 65,000 GALS  TAC AND REMAINING TBG & SN TO 8,575', SE  S. PUT ON PRODUCTION.  PAYE NOKES THE PROD. MG	S WF-30 & 118,740# ET TAC @ 8,251'. N	2s 20-40 ECONOPRO  ID BOP NU WH.		
3. 3-14-95 FRAC BONE 4. 3-15-95 GIH w/ TBG RUN PUMP & ROD  14. I hereby certify that the strengting to  Signed  (This space for Edderal or State of Approved by	E SPRING PERFS 8761-8824' (OA) w/ 65,000 GALS  TAC AND REMAINING TBG & SN TO 8,575', SE  S. PUT ON PRODUCTION.  PAYE NOKES THE PROD. MG	S WF-30 & 118,740# ET TAC @ 8,251'. N	2s 20-40 ECONOPRO  ID BOP NU WH.		

-7/