

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-32647
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name McCallister State
8. Well No. 11
9. Pool name or Wildcat Vacuum: Wolfcamp, Abo & U. Penn
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL 4013' KB 4026'

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator Marathon Oil Company	3. Address of Operator P.O. Box 2490 Hobbs, NM 88240
4. Well Location Unit Letter K : 1927' Feet From The South Line and 2134' Feet From The West Line Section 25 Township 17S Range 34E NMPM Lea County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL 4013' KB 4026'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: **Recomplete Vacuum: Blinbry** ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1/12 MIRU pulling unit. POOH w/rods. ND wellhead. NU BOP. Rel TAC, POOH w/2 7/8" prod tbg. RIH w/bit & scrapper to 7200'. POOH. RIH w/RBP & pkr. Set RBP at 7157', pkr at 7126'. Test, OK. Reset pkr at 6717'. Pickle tbg w/500 gal 15% acid. Spotted 250 gals 15% acid across lower Blinbry.
1/14 POOH w/pkr, Perforate 6663-69', 6693-6701', 6708-12', 4 SPF. RIH w/pkr, set at 6540'. Acidize w/1000 gals acid w/100 BS. Sand frac w/31,752 gals Delta Frac w/523 sxs of 16/30 sand followed by 194 sxs 16/30 Super LC sand. Flowed well.
1/20 RIH rel pkr at 6540', POOH. RIH w/RBP & pkr. Set RBP at 6600'. Spot 250 gals 15% across 6412-6504'. POOH w/pkr. Perf 6412-14', 6441-47', 6486-6504', 4 SPF. RIH w/pkr. Set at 6350'. Acidize w/1500 gals acid w/150 BS. Swab. Sand frac w/35,500 gals Delta Frac w/520 sxs 16/30 Super LC RC sand. Flow well. Rel pkr, POOH. Clean out. Rel RBP, POOH. RIH, set pkr at 6350'. Swab. Run after frac logs 6000-7130'. Rel pkr, clean out sand. Rel RBP 7157', POOH.
2/3 RIH w/2 7/8" tbg. Set TAC. NU wellhead. RIH w/pump & rods. Load & test, OK. RD pulling unit.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kelly Cook TITLE Records Processor DATE 4/8/99
TYPE OR PRINT NAME Kelly Cook TELEPHONE NO. 393-7106

(This space for State Use)

APR 08 1999

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: