

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-33113
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Royal State
8. Well No. 1
9. Pool name or Wildcat Vacuum; Blinebry, East
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL 3941'; KB 3960.5'

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator Marathon Oil Company	
3. Address of Operator P.O. Box 2409, Hobbs, NM 88240	
4. Well Location Unit Letter I : 2210 Feet From The South Line and 1310 Feet From The East Line Section 33 Township 17-S Range 35-E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL 3941'; KB 3960.5'	

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: **Frac Upper & Lower Blinebry** ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3/10/98 MIRU PU. RIH w/RBP & pkr. Set RBP at 7410', pkr at 7326'. Test, rel pkr, reset at 7070'.

3/12/98 Frac Lower Blinebry 7116-7190' w/2000 gals 15% acid & 23,000 gals of crosslinked gel w/650 sxs 20/40 Ottawa sand. Swab well. Rel pkr, POOH. Run RBP overshot w/bailer. Clean out sand. Rel RBP & reset at 7055'. RIH set pkr at 7030'. Test RBP. Rel pkr, reset at 6655'.

3/17/98 Frac Upper Blinebry 6761-6971' w/4000 gals 15% acid, w/70,000 gals crosslinked gel & 1700 sxs 20/40 sand. Rel pkr at 6655', POOH. Run RBP overshot w/bailer. Clean out sand. POOH. RIH w/pkr, set at 6715'. Swab well.

3/25/98 RIH rel pkr at 6715', POOH. RIH w/RBP overshot, rel RBP at 7055'. POOH. RIH w/prod tbg. RIH w/pump & rods. RD PU.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kelly Cook TITLE Records Processor DATE 4/7/98
TYPE OR PRINT NAME Kelly Cook TELEPHONE NO. 393-7106

(This space for State Use)

ORIGINAL SIGNED BY CHRIS WILLIAMS
DISTRICT SUPERVISOR

APPROVED BY _____ TITLE _____ DATE APR 14 1998
CONDITIONS OF APPROVAL, IF ANY: _____