

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-33148
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	B-155
7. Lease Name or Unit Agreement Name	NEW MEXICO O STATE NCT-1
8. Well No.	38
9. Pool Name or Wildcat	VACUUM WOLFCAMP
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3987' GR	

SUNDRY NOTICES AND REPORTS ON WELL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>I</u> : <u>2085</u> Feet From The <u>SOUTH</u> Line and <u>710</u> Feet From The <u>EAST</u> Line Section <u>36</u> Township <u>17-S</u> Range <u>34-E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3987' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPERATION <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-20-97: MIRU. WRK STUCK RODS. TBG PARTED. NUBOP. TIH W/OVERSHOT. LATCH ON @ 17'.
10-21-97: WRK STUCK TBG. SCREW INTO FSH. LAND TABG.
10-22-97: TIH & LATCH ONTO RODS.
10-23-97: NUBOP. WRK STUCK TBG. RUN FREE POINT. CHEM CUT @ 9488'.
10-24-97: TIH W/OVERSHOT, BS, JARS, DC'S & SUB. TBG @ 2212'.
10-25-97: LATCH ONTO TBG @ 9481'. JAR STUCK TBG. RECVD ALL OF FSH.
10-27-97: LDDC & FSH. TIH W/PKR & SET @ 9050'.
10-28-97: ACIDIZE PERFS 9280-10118' W/10000 GALS 15% NEFE & 700 BALL SEALERS.
10-29-97: SCALE SQUEEZE W/2 DRUMS TH 756 & FLSH W/250 BBLS 2% KCL.
10-30-97: TIH W/PROD TBG & PMP.
10-31-97: HANG WELL ON. RD.
11-03-97: ON 24 HR OPT. PUMPED 24 BO, 94 BW, & 53 MCFD. STATUS IS PUMPING.
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 2/4/98

TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

ORIGINAL SIGNED BY CHRIS WILLIAMS
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: