Submit 3 Copies to Appropriate

CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

District Office				
DISTRICT I P.O. Box 1980, Hobbs NM 88241-1980	IL CONSERVATIO		WELL API NO.	
P.O. Box 1980, Hobbs NM 88241-1980 P.O. Box 2088 DISTRICT II Santa Fe, New Mexico 87504-2088			30-025-33307	
P.O. Drawer DD, Artesia, NM 88210			5. Indicate Type of Lease	re 🗓 FEE
DISTRICT III			6. State Oil & Gas Lease No.	
1000 Rio Brazos Rd., Aztec, NM 87410			B-1414-2	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"				
			7. Lease Name or Unit Agree	ement Name
(FORM C-101) FOR SUCH PROPOSALS.)			STATE RIDGE "B"	
I. Type of Well: OIL GAS WELL WELL X				
	OTHER			
2. Name of Operator			8. Well No.	
Shell Western E&P, Inc. 3. Address of Operator			9. Pool name or Wildcat	
P. O. BOX 576 HOUSTON, TX 77001 ATTN. YVONNE T. IVERSON			WILDCAT More	row
4. Well Location	601711		0'	EAST Line
Unit Letter I : 2310'	Feet From The SOUTH	Line and99	Feet From The	Line Line
Section SECTION 30	Township 17S Ra	nge 35E	NMPM LEA	County
	10. Elevation (Show whether	er DF, RKB, RT, GR, etc	:.)	
	//// <u>///</u>	3979'	<u> </u>	<u>'////////////////////////////////////</u>
	opriate Box to Indicate	1	- :	
NOTICE OF INT	ENTION TO:	SUB	SEQUENT REPO)RT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	AI TERIN	g CASING
TEMPORARILY ABANDON	CHANGE PLANS L	COMMENCE DRILLING	OPNS. LI PLUGIAN	ID ABANDONMENT L
PULL OR ALTER CASING		CASING TEST AND CE	MENT JOB	
OTHER:		OTHER: TESTEL	MORROW & ATOKA FORM	MATIONS. X
12. Describe Proposed or Completed Operati work) SEE RULE 1103.				
out to 11,631'. Perf t oil, 0 wtr, 1,065 mcf/	report. Drld out soft come he Morrow zone from 11,55 d. Tbg psi 1050. Perf the loil an hr, 1,194 mcf/d	24'-11,532'. 24 hr e Morrow intv addl	flg test-14/64 chk, 2' from 11,518'-11.	208 bb1s
nipple abv pkr. After Unable to shut well in held OK. Pld 1.875 plu blanking plug & set in tbefrom on/off tool & RIH w/359 jts 2-3/8 ne	tree & inst BOP. RIH w/1 several attempts, plug hared over night. Plug. RIH w/1.81 blanking plug. RIH w/1.81 blanking plug. RIH w/Baker 5-1/2" w N-80 tbg. Set pkr @11	eld OK. Plug start d blanking plug fr lug in F nipple be . After 2 hrs-chk full bore PKR, XL ,315'. C-103 REPOR	ed leaking 2 hrs aft om well. RIH w/2nd p low pkr. Plug held 0 for leak. Plug held on/off tool w/1.87 F	er setting. lug. Plug K. Ran OK. Rlsed nipple.
I hereby certify that the information above is true	Λ	e and belief.		1 1 1 1
SIGNATURE Y WARRE V.	WSM THI	LE <u>LAND REPRESEN</u>	TATIVE DATE	<u> 7 30 94</u>
TYPE OR PRINT NAME YVONNE T	IVERSON		TELEPHONE	NO. (713)544-3226
(This space for State Use) Orig. Sig	ned by Jausz			
APPROVED BYGenlo		LE	DATE_	AUG UZ 10