

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-33711

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil / Gas Lease No.

B-155-1

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator
205 E. Bender, HOBBS, NM 88240

4. Well Location

Unit Letter G : 2000 Feet From The NORTH Line and 2630 Feet From The EAST Line
Section 36 Township 17-S Range 34-E NMPM LEA COUNTY

10. Elevation (Show whether DF, RKB, RT,GR, etc.) 3996' GR

7. Lease Name or Unit Agreement Name

CENTRAL VACUUM UNIT

8. Well No.
167

9. Pool Name or Wildcat
VACUUM GRAYBURG SAN ANDRES

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒

ALTERING CASING ☐

COMMENCE DRILLING OPERATION ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

HORIZONTAL ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-03-99: MIRU KEY RIG #119. NUBOP. RU GAS BUSTER TO FLOWLINE. PU MILLS & PU DP. TAG RBP. PU & MAKE UP WHIPSTOCK & SET. MILL 4238-4239.

11-04-99: MILL 4244-4250, 4252, 4281, 4312, 4325, 4442, 4502, 4596, 4606, 4660, 4670, 4787, 4802, 4819, 4834, 4850, 4860, 4985, 4999, 5007, 5022, 5038, 5053, 5069, 5089, 5101, 5105, 5125, 5133, 5153, 5164, 5179, 5301. TIH W/MAGNET.

11-08-99: REAM 5227-5301, ROTATE 5301-5322, 5334, 5386, 5391, 5417, 5418, 5497. TD HLE 11-8-99

11-09-99: JAR ON WHIPSTOCK. TIH W/RBP & SET @ 4100'. TEST TO 800 PSI.

11-10-99: NDBOP0. NU BOP & TEST TO 500 PSI. REL RIG 11-9-99.

11-12-99: MIRU SERV UNIT.

11-13-99: REL RBP. PU BENT SUB, TBG, PKR.

11-14-99: FLOW WELL TO TEST TANK. PUMP 40 BBLS BRINE DN BACKSIDE. TIH W/3 1/2" TBG. SET PKR @ 4150'. NU TREE. RD SERV UNIT.

11-17-99: MIRU FRAC CREWS. ACIDIZE GRAYBURG SAN ANDRES W/30,000 GALS 20% HCL & 30,000 GALS WF130.

11-18-99: MIRUSU. KILL WELL. REL PKR. C/O RAMS INSTL BLIND RAMS IN BOP. TIH W/RETR TOOL TO 1890'.

11-19-99: PU TBG. CIRC SAND OFF TOP OF RBP & SET @ 4256'. LATCH ONTO RBP. TIH W/KILL STRING TO 2500'.

11-20-99: KILL W/10 PPG BRINE. TIH W/PROD EQPT: MOTOR, SEAL, GAS SEPR, PUMP, PUMP @ 4217'. NDBOP EQPT. INSTL WH. START WELL PUMPING.

11-28-99: ON 24 HR OPT. PUMPED 239 BO, 252 BW, & 301 MCF.

FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

J. Denise Leake

TITLE

Engineering Assistant

DATE 12/14/99

TYPE OR PRINT NAME

J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL IF ANY:

TITLE

DATE