

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-33893
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Summers Neal
8. Well No. 1
9. Pool name or Wildcat South Knowles (Devonian)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator Rand Paulson Oil Company, Inc.	
3. Address of Operator 508 W. Wall, Ste 100, Midland, Texas 79701	
4. Well Location Unit Letter <u>J</u> : <u>2040</u> Feet From The <u>South</u> Line and <u>2040</u> Feet From The <u>East</u> Line Section <u>18</u> Township <u>17-S</u> Range <u>39-E</u> NMPM <u>Lea</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3656' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☒ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spud well 7:30 PM 3-30-97. Drill 17 1/2" hole to 447'. Ran 13 3/8" 48# J-55 STC casing to 447'. Cemented w/500 sx Class C + 2% CaCl². Circ 20 sx to surface. WOC 24 hrs. Cut off casing. Install well head. NU BOP. Test casing to 600 psi. Test BOP, head & manifold to 1500 psi. Drill 11" hole to 4803'. Ran 8 5/8" 32# S-80 and J-55 casing. Cemented w/1475 sx C + 3% D-79. Tail in w/200 sx C Neat. Circ 85 sx to surface, WOC 24 hrs. Cut off casing. NU BOP, install head. Test BOP, head and manifold to 1500 psi. Test casing to 1000 psi. DO floats. Drilling 7 7/8 hole, 4-7-97.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Agent DATE 4-7-97

TYPE OR PRINT NAME O.H. Routh

TELEPHONE NO 915/687-032

(This space for State Use)

ORIGINAL SIGNED BY
GARY WINK
FIELD REP II

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: