	5 of New Mexico			Form C-103
Submit 3 Copie	Energy, Minerals and Natural Resources I	Department		Revised 1-1-89
Distait Office				
DISTRICT I OIL CONSERVATION DIVISION				
······································	2040 South Pacheco		WELL API NO.	
P.O. Box 1980, Hobbs, NM 88241-1980 Santa Fe, New Mexico 87505		30-025-34059		
DISTRICT II			5. Indicate Type of Lease	
811 S. First Street, Artesia, NM 88210			STATE	X FEE
			6. State Oil & Gas Lesse No.	
DISTRICT III			K-6023	
1000 Rio Brazos Rd., Aztas, NM 87410				
SUNDRY	NOTICES AND REPORTS ON WELLS		7. Lesse Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PR	OPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A ESERVOIR. USE "APPLICATION FOR PERMIT"	4	/. Dene ivalise of offici registration of the	
	FORM C-101) FOR SUCH PROPOSALS.)			
1. Type of Well:				
	OTHER		POWERPRO 20	
		8. Well No.		
. Namia of Operator	010010/		1	
ELK OIL CO			9. Pool Name or Wildort	
3. Address of Operator				
POST OFF	ICE BOX 310, ROSWELL, NEW MEXICO	88202-0310	VACUUM ABO NORTH	
4. Well Location			660 Feet From The	WEST Line
Unit Letter E	:1760 Feet From The NOR IH	Line and		
20 17 SOUTH Barry 35 EAST NMPM LEA County				
Section 20	Township 17 SOUTH 10. Elevation (Show whather DF, RKB, RT	mag.		
	3978' GR	ura of Notice Ren	ort or Other Data	
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF:				
NOTICE OF IN	ITENTION TO:		SUBSEQUENT REPORT OF	
-			X ALTERING CASH	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASH	
- r		COMMENCE DRILLING	DORNS PLUG AND ABAN	IDONMENT
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING		
CASING TEST AND CEM			MENTJOB	
PULL OR ALTER CASING			·	1
		OTHER:		
OTHER:			time and mark	· · · · · · · · · · · · · · · · · · ·
12. Describe Proposed or Completed Operations (Clearly state all pertinent datails, and give pertinent dates, including estimated date of starting any proposed work)				
SEE RULE 1103				
April 27, 2000 through May 3, 2000:				
Pull out of hole with tubing. Set EZSV retainer at 8665'. Squeeze existing perforations at 8754'-8778' with 50 sxs cement.				
Test to 1700#, held okay. Run in hole with tubing to 8591'. Shut down, waiting for rig.				
May 10, 2000 through May 19, 2000: Rig up Pool. Set whipstock at 8627'. Mill window. Pick up motor and MWD. Drill and slide to 10,074'. Pull out of hole with				
Rig up Pool. Set whipstock at 8027. Will willow. Fick up motor and wirdb. Brill and onde to rejet the set of the				
motor and MV	VD. Run in hole with tubing to 8600'. Rig (	aown Pool.		
Mar. 00. 0000				
Rig un nulling	unit. Pull out of hole with tubing. Run in ho	ole with tubing to 8	3650'. Pick up rods and pump.	
	· · · · · ·			
May 21, 2000: Produced 15 oil, 30 water, 30 MCF. Rig down pulling unit.				
Produced 15 d	oll, 30 water, 30 MCr. Rig down pulling ut			
	See continuation of report on attac	nea sneet.		<u></u>
I hereby certify that the information above is	a true and complete to the best of my knowledge and belief.			
	Z TITLE PRE	SIDENT	DATE	7/19/00
SIGNATURE				505-623-3190
TYPE OR PRINT NAME	JOSEPHYJ. KELLY		TELEPHONE NO.	JUJ-UZ-J170
(This space for State Use)	1			
÷ ,	DISTRUCT D		DATE	
APPROVED BY CONDITIONS OF APPROVAL, IF ANY:				

5