

**DISTRICT I**  
P.O. Box 1980, Hobbs, NM 88240

**DISTRICT II**  
P.O. Drawer DD, Artesia, NM 88210

**DISTRICT III**  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-34059
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	
Powerpro 20	
8. Well No.	1
9. Pool name or Wildcat	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
3997' KB	

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> Dry Hole	
2. Name of Operator Altura Energy LTD	
3. Address of Operator P.O. Box 4294, Houston, Texas 77210-4294	
4. Well Location Unit Letter <u>E</u> : <u>1760</u> Feet From The <u>North</u> Line and <u>660</u> Feet From The <u>West</u> Line Section <u>20</u> Township <u>17-S</u> Range <u>35-E</u> NMPM <u>Lea</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3997' KB	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8/30/97 Received plugging instructions from Paul Kautz at the NMOCD.

8/31/97 Spot 40 sx. cement plug (Cl. 'H' neat) at TD.

9/1/97 Mix x displace 2nd 40 sx. bottom hole plug (Cl. 'H' neat).

9/2/97 Spot 40 sx. plug at 10,455'; spot 35 sx. plug at 8230'; spot 40 sx. plug at 6115'; spot 40 sx. plug at 5052' (50' below casing shoe); spot 30 sx. plug at 1750'; spot 10 sx. plug at surface (all plugs Cl. 'H' neat cement). ND BOP equipment x clean pits. Release rig at 0600 hrs. Set dry hole marker.

Waiting on State Inspection

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mark Stephens TITLE Business Analyst (SG) DATE 10/14/97  
TYPE OR PRINT NAME Mark Stephens TELEPHONE NO. (281) 552-1158

(This space for State Use)

**FOR RECORD ONLY**

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

JCT

dp