

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

Amended Report

WELL API NO.

30-025-34668

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil / Gas Lease No.

7. Lease Name or Unit Agreement Name

NORTH VACUUM ABO WEST UNIT

8. Well No.

29

9. Pool Name or Wildcat

VACUUM ABO NORTH

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator
205 E. Bender, HOBBS, NM 88240

4. Well Location

* SHL Unit Letter O : 365 Feet From The SOUTH Line and 1880 Feet From The EAST Line

Section 21 Township 17-S Range 34-E NMPM LEA COUNTY

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

4057'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒

ALTERING CASING ☐

COMMENCE DRILLING OPERATION ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☒ SPUD & SURFACE CSG

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-07-99: SPUD 11" HLE @ 0530 11/6/99. DRILL 0-1572', 1620. TD 11" HLE @ 0700 11/7/99. RUN FREE POINT. REAMER STUCK @ 1320. REAM 155' TO BTM. RAN 36 JTS 8 5/8" 28# NS55, LTC CSG & SET @ 1620'. CMT W/500 SX CL 4% GEL, 2% CACL2, 13.5 PPG, & 150 SX CL C 2% CACL2, 14.8 PPG. PLUG DOWN @ 0500 11/9/99. CIRC 46 BBLs TO SURF. WOC. C/O 8 5/8" CSG & TEST TO 700 PSI. NUBOP STACK. DRILL 1620-1717, 2037, 2161, 2224, 2508, 2827, 2978, 3353, 3375, 3477, 3577, 3665, 3745, 3922, 3947, 4010, 4148, 4265, 4359, 4420, 4482, 4500, 4517, 4544, 4668, 4750, 4852, 5014, 5046, 5070, 5108, 5337, 5357, 5481, 5630, 5637, 5886, 5892, 6014, 6208, 6264, 6327, 6422, 6620, 6672, 6732, 6735, 6829, 6890, 6923, 7048, 7174, 7218, 7301, 7424, 7520, 7545, 7645, 7739, 7797, 7832, 7909, 7914, 7919, 7992, 8149, 8190, 8200, 8212, 8307, 8390, 8419, 8433, 8496, 8506, 8591, 8608, 8685, 8720, 8812 PU CORE BARREL FOR CORE #1. CUT CORE FR 8812-8832, 8836, 8872. TIH W/CORE BBL FOR CORE #2. REAM 30' TO BTM. CORE 8872-8877, 8932. TIH TO 8812' W/RE-RUN BIT & REAMERS. REAM FR 8812-8932'. DRILL FR 8932-9000'. TD 7 7/8" HLE @ 0100 HRS ON 11/29/99.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *J. Denise Leake* TITLE Engineering Assistant

DATE 11/30/99

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL, IF ANY: TITLE

DATE