Stal ... w Mexico

Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

<u>DISTRICT 1</u> P.O. Box 1980, Hobbs NM 88240	OIL CONSERVATION DIVISION 2040 South Pacheco			API NO.		
DISTRICT II	ISTRICT II Santa Fe, New Mexico 87505			30-025-35263		
811 South First, Artesia, NM 88210			5. Indic	ate Type of Lease STATE	☐ FEE ☒	
DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410			6. State	Oil & Gas Lease No.		
SUNDRY NOT	ICES AND REPORTS O	N WELLS	2.704	Company (September		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS).			TO A 7. Lease	e Name or Unit Agreeme	nt Name	
1. Type Of Well: OIL GAS						
WELL WELL L. OTHER				Charles S. Alves		
2. Name of Operator Mack Energy Corporation			8. Well 5	8. Well No.		
3. Address of Operator				9. Pool name or Wildcat		
P.O. Box 960, Artesia, NM 88211-0	960		Scharb	Bone Springs		
Unit Letter <u>G</u> : <u>1720</u>	Feet From The No	orth Line and	1720	Feet From The	East Line	
Section 7	Township 19S	Range 35I	E NMPM	Lea	County	
		hether DF, RKB, RT, Gl		ALCONO IS		
11. Check A	mananista Day ta India	3874 GR	-4' D	NAME AND ADDRESS OF THE PARTY O		
NOTICE OF INT	ppropriate Box to Indic ENTION TO:	cate Nature of No	-	or Other Data ENT REPORT (OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIALV	VORK	ALTERING (CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE	DRILLING OPNS.	PLUGANDA	ABANDONMENT	
PULL OR ALTER CASING			T AND CEMENT JO		L de Control Livi	
OTHER:		OTHER				
12. Describe Proposed or Completed Opwork SEE RULE 1103.	crations (Clearly state all pertiner	nt details, and give pertine	ent dates, including esti	mated date of starting any p	proposed	
·	Plug and Abandon as follo	WS: - 4 C				
Mack Energy Corporation proposes to 1. Set CIBP 100' above perfs at 9906'	w/35' of cement on top.	TAG				
 Circulate hole w/mud. Set 100' cement plug 50' above and Set 100' cement plug 50' above and 	halow intermediate engine	1004 2004 - 7	ig			
4. Set 100' cement plug 50' above and	below surface casing 468-3	68'. ~T'AG		21011121379		
5. Set 10sx plug at surface.	0	77.0	18	3	\	
5. Install dry hole marker.			(3)	1, and	لير	
- 50- 100 AG	MEATT PINA 1	850+0195	D 7 8	DEC ED	8	
J 281 100 CZ1	MEMITOUS.	(TOP of	5ALD 12	KL - This	8	
	below intermediate casing below surface casing 468-3	•	//	AOCD V	27/	
			100			
				15 8572 82 25 25 25 25 25 25 25 25 25 25 25 25 25		
I hereby certify that the information above is true a	nd complete to the best of my knowled	ge and belief.				
SIGNATURE SENSE W.	honell	TITLE	Production Clerk	DATE	12/7/01	
TYPE OR PRINT NAME	Jerry W	. Sherrell		TELEPHON	ENO. 748-1288	
(This space for State Use)			- 10 CM			