

DISTRICT I
P.O. Box 1980, Hobbs NM 88240

DISTRICT II
811 South First, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd, Aztec, NM 87410

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, New Mexico 87505

WELL API NO. 30-025-35263
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Charles S. Alves
8. Well No. 5
9. Pool name or Wildcat Scharb Bone Springs 55610
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3874 GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS).

1. Type Of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER
2. Name of Operator Mack Energy Corporation
3. Address of Operator P.O. Box 960, Artesia, NM 88211-0960
4. Well Location Unit Letter G : 1720 Feet From The North Line and 1720 Feet From The East Line Section 7 Township 19S Range 35E NMPM Lea, NM County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3874 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	
OTHER: <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER <input checked="" type="checkbox"/>	Completion <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

01/30/2001 Drill out DV tool.
01/31/2001 Perforate 10105-10136' 4/SPF 128 holes 0.42 hole.
02/01/2001 Acidize tubing w/400 gals 15% acid, reverse out, spot 2 bbls acid, start 3000 gal acid 15%.
02/03/2001 RIH w/2 7/8" L-80 EUE 6.5# tubing 324 joints SN @ 10,146'.
02/05/2001 RIH w/2 1/2 x 1 1/2 x 24' PAP Pull Rod.
03/19/2001 RIH w/2 7/8" L-80 6.5# tubing 324 joints SN @ 10,146', RIH w/2 1/2 x 1 1/2 x 24' PAP Pull Rod.
06/04/2001 POH w/2 1/2 x 1 1/2 x 24' RH pump.
06/05/2001 RIH w/82' ESP Submersible pump, 319 joints 2 7/8" L-80 tubing SN @ 9976', bottom of pump @ 10,058', pumping at 5:30 PM.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jerry W. Sherrell TITLE Production Clerk DATE 6/28/01
TYPE OR PRINT NAME Jerry W. Sherrell TELEPHONE NO. 748-1288

(This space for State Use)

APPROVED BY _____ TITLE Paul Kautz DATE 6/28/01
CONDITIONS OF APPROVAL, IF ANY: