

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-35392
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: TMBR "14" State
7. Well No. 1
9. Pool name or Wildcat Vacuum; Blinebry, NE

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
TMBR/Sharp Drilling, Inc.

3. Address of Operator
P. O. Drawer 10970, Midland, TX 79702

4. Well Location

Unit Letter I : 1650 feet from the South line and 330 feet from the East line
Section 14 Township 17S Range 35E NMPM Lea County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
GR 3917'

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:
REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Bradenhead Squeeze ☒

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

See attached sheet.

RECEIVED
MAR 26 2003
HOBBS
DND

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Production Manager DATE 02/26/03

Type or print name Lonnie Arnold Telephone No. (915) 699-5050
(This space for State use)

APPROVED BY _____ ORIGINAL SIGNED BY _____ DATE MAR 04 2003
Conditions of approval, if any: GARY W. WINK
OC FIELD REPRESENTATIVE II/STAFF MANAGER

TMBR/SHARP DRILLING, INC.
TMBR "14" State No. 1
1650' FSL & 330' FEL
Sec. 14, T-17S, R-35E
Lea County, NM

BRADENHEAD SQUEEZE

- 01/25/03 PO: Prep to bradenhead squeeze.
MIRU TWS. POH w/pump. NU BOP, release TAC. POH w/2¾" tbg. Gih w/RbP & pkr. Set RBP @ 6725', set pkr @ 6700'. Load tbg w/2% KCL. Press to 500 psi, ok. Open bypass, load csg w/2% KCL, press to 500 psi, ok. Secure well.
- 01/26/03 SD for weekend.
thru
01/27/03
- 01/28/03 PO: PO: Prep to pull RBP.
SICP 0 psi, SI bradenhead press 310 psi. POH w/pkr. RU BJ Service. Load 5 ½" w/2% KCL. Press to 500 psi, ok. Bled bradenhead press down, establish injection rate of 2 BPM, 1300 psi. Pump 56 sx CI "H" thickset 14.6 ppm, 1.5 cu.ft./sk yield. Tail w/270 sx CI "C", 14.8 ppg, 1.33 cu.ft. yield, 2 BPM, 1200 psi. SD ¼ hr, 790 psi. Displace 1 BW, 790 psi. RD BJ Service. Secure well.
- 01/29/03 PO: RD.
SICP 0 psi, SI bradenhead 110 psi. Bled bradenhead down 1 min, no blow or flow. GIH w/retrieving tool. Release RBP & POH. TIH w/SN & TAC. ND BOP, set TAC, nU wellhead. GIH w/pump & rods, space out. Load tbg w/15 BBL 2% KCL. Stroke unit 500 psi in 5 strokes, held ok. Secure well.
- 01/30/03 Good pump action. RD TWS. Left on POC. Turn over to pumper. No rod or tbg changes.
FINAL REPORT.

Hobbs
000