Submit 3 Copies to Appropriate District Office	State of New M Energy, Minerals and Natural I		Form C-103 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION P.O. Box 20)88	WELL API NO. 30-025-35931
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico	6 87504-2088	5. Indicate Type of Lease STATE X FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 874	10		6. State Cil & Gas Lease No. 29154
(DO NOT USE THIS FORM FOR DIFFERENT RE	OTICES AND REPORTS ON WE PROPOSALS TO DRILL OR TO DEEPE ESERVOIR. USE "APPLICATION FOR P IM C-101) FOR SUCH PROPOSALS.)	N OF PLUG BACK TO A	7. Lease Name or Unit Agreement Name Gach "31" State
1. Type of Well: OIL GAS WELL WELL	X		
2. Name of Operator			8. Well No.
3. Address of Operator 4001 Pe Odessa	s Petroleum Company enbrook Street Texas 79762		9. Pool name or Wildcat Vacuum; Morrow
4. Well Location Unit Letter <u>K</u> :	1980 Feet From The South	Line and <u>15</u>	500 Feet From The West Line
Section 31	Township 17S 1 10. Elevation (Show whethe 4096 ' GL		NMPM Lea County
	INTENTION TO:	SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS	FIEMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	CHANGE PLANS	COMMENCE DRILLING CASING TEST AND CE OTHER:	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed G work) SEE RULE 1103.	CHANGE PLANS	COMMENCE DRILLING CASING TEST AND CE OTHER: and give pertinent dates, inclu	G OPNS. X PLUG AND ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed G work) SEE RULE 1103. 06/30/02 Moved in & ri	CHANGE PLANS	COMMENCE DRILLING CASING TEST AND CE OTHER: and give pertinent dates, inclu	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed (work) SEE RULE 1103. 06/30/02 Moved in & ri @8 p.m. 06/29 07/01/02 Drilled/surve "C" w/2% CCL Nipple up &	CHANGE PLANS	COMMENCE DRILLING CASING TEST AND CE OTHER: and give pertinent dates, inclu- cilling Co. Rig # ' 48# casing, set cculated 75 sx to	GOPNS. X PLUG AND ABANDONMENT EMENT JOB ding estimated date of starting any proposed #75. Drilled 184'. Spudded well t @446'. Cemented w/250 sx class o pit. Waited on cement 4 ¹ / ₂ hrs.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed (work) SEE RULE 1103. 06/30/02 Moved in & ri @8 p.m. 06/29 07/01/02 Drilled/surve "C" w/2% CCL Nipple up & 07/02/02 Drilled cemen 07/03/02 Drilled/surve	CHANGE PLANS	COMMENCE DRILLING CASING TEST AND CE OTHER: and give pertinent dates, inclu- cilling Co. Rig # ' 48# casing, set cculated 75 sx to Drilled/surveyed	GOPNS. X PLUG AND ABANDONMENT EMENT JOB ding estimated date of starting any proposed 475. Drilled 184'. Spudded well t @446' Cemented w/250 sx class o pit. Waited on cement 4 ¹ / ₂ hrs. d. Bit #2 in @447 ^{1,056786}
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed (work) SEE RULE 1103. 06/30/02 Moved in & ri @8 p.m. 06/29 07/01/02 Drilled/surve "C" w/2% CCL Nipple up & 07/02/02 Drilled cemen 07/03/02 Drilled/surve 07/04/02 Trip & change 07/05/02 Drilled/surve	CHANGE PLANS	COMMENCE DRILLING CASING TEST AND CE OTHER: and give pertinent dates, inclu- cilling Co. Rig # ' 48# casing, set cculated 75 sx to Drilled/surveyed	GOPNS. X PLUG AND ABANDONMENT EMENT JOB ding estimated date of starting any proposed 475. Drilled 184'. Spudded well t @446' Cemented w/250 sx class o pit. Waited on cement 4 ¹ / ₂ hrs. d. Bit #2 in @447 ^{1,056786}
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed (work) SEE RULE 1103. 16/30/02 Moved in & ri (@8 p.m. 06/29) 17/01/02 Drilled/surve "C" w/2% CCL Nipple up & 17/02/02 Drilled/surve 17/03/02 Drilled/surve 17/05/02 Drilled/surve 17/06/02 Drilled/surve	CHANGE PLANS	COMMENCE DRILLING CASING TEST AND CE OTHER: and give pertinent dates, inclu- cilling Co. Rig # ' 48# casing, set cculated 75 sx to Drilled/surveyed	GOPNS. X PLUG AND ABANDONMENT EMENT JOB ding estimated date of starting any proposed 475. Drilled 184'. Spudded well t @446' Cemented w/250 sx class o pit. Waited on cement 4 ¹ / ₂ hrs. d. Bit #2 in @447 ^{1,05678}
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed (work) SEE RULE 1103. 06/30/02 Moved in & ri @8 p.m. 06/29 07/01/02 Drilled/surve "C" w/2% CCL Nipple up & 07/02/02 Drilled/surve 07/03/02 Drilled/surve 07/05/02 Drilled/surve 07/06/02 Drilled/surve 07/08/02 Drilled/surve 07/08/02 Drilled/surve 07/09/02 Drilled/surve	CHANGE PLANS	COMMENCE DRILLING CASING TEST AND CE OTHER: and give pertinent dates, inclu- cilling Co. Rig # ' 48# casing, set cculated 75 sx to Drilled/surveyed.	GOPNS. X PLUG AND ABANDONMENT EMENT JOB ding estimated date of starting any proposed 475. Drilled 184'. Spudded well t @446' Cemented w/250 sx class o pit. Waited on cement 4 ¹ / ₂ hrs. d. Bit #2 in @447 ^{1,056786}
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed (work) SEE RULE 1103. 06/30/02 Moved in & ri @8 p.m. 06/29 07/01/02 Drilled/surve "C" w/2% CCL Nipple up & 07/02/02 Drilled/surve 07/03/02 Drilled/surve 07/05/02 Drilled/surve 07/06/02 Drilled/surve 07/08/02 Drilled/surve 07/09/02 Drilled/surve 07/09/02 Drilled/surve 07/09/02 Drilled/surve 07/10/02 Drilled/surve 07/10/02 Drilled/surve 07/10/02 Drilled/surve 07/10/02 Drilled/surve 07/10/02 Drilled/surve	CHANGE PLANS	COMMENCE DRILLING CASING TEST AND CE OTHER: and give pertiment dates, inclu- cilling Co. Rig # ' 48# casing, set culated 75 sx to Drilled/surveyed illed/surveyed.	GOPNS. X PLUG AND ABANDONMENT EMENT JOB ding estimated date of starting any proposed 475. Drilled 184'. Spudded well t @446' Cemented w/250 sx class o pit. Waited on cement 4 ¹ / ₂ hrs. d. Bit #2 in @447 ^{1,056786}
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed (work) SEE RULE 1103. 06/30/02 Moved in & ri (@8 p.m. 06/29) 07/01/02 Drilled/surve "C" w/2% CCL Nipple up & 07/02/02 Drilled/surve 07/03/02 Drilled/surve 07/05/02 Drilled/surve 07/06/02 Drilled/surve 07/06/02 Drilled/surve 07/08/02 Drilled/surve 07/09/02 Drilled/surve 07/09/02 Drilled. Thereby certify that the information above	CHANGE PLANS	COMMENCE DRILLING CASING TEST AND CE OTHER: and give pertinent dates, inclu- cilling Co. Rig # ' 48# casing, set culated 75 sx to Drilled/surveyed illed/surveyed.	GOPNS. X PLUG AND ABANDONMENT EMENT JOB ding estimated date of starting any proposed 475. Drilled 184'. Spudded well t @446'. Cemented w/250 sx class b pit. Waited on cement 4 ¹ / ₂ hrs. d. Bit #2 in @447 ^{11.5670} Bit #3 in 2800'. 900 (77
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed (work) SEE RULE 1103. 06/30/02 Moved in & ri @8 p.m. 06/29 07/01/02 Drilled/surve "C" w/2% CCL Nipple up & 07/02/02 Drilled/surve 07/03/02 Drilled/surve 07/05/02 Drilled/surve 07/06/02 Drilled/surve 07/06/02 Drilled/surve 07/08/02 Drilled/surve 07/08/02 Drilled/surve 07/08/02 Drilled/surve 07/09/02 Drilled/surve 07/09/02 Drilled/surve 07/10/02 Drilled/surve 07/10/02 Drilled/surve 07/10/02 Drilled/surve 07/10/02 Drilled/surve 07/10/02 Drilled/surve 07/10/02 Drilled/surve Norve Signature	CHANGE PLANS	COMMENCE DRILLING CASING TEST AND CE OTHER: and give pertinent dates, inclu- cilling Co. Rig # ' 48# casing, set culated 75 sx to Drilled/surveyed illed/surveyed.	GOPNS. X PLUG AND ABANDONMENT EMENT JOB ding estimated date of starting any proposed 475. Drilled 184'. Spudded well t @446'. Cemented w/250 sx class b pit. Waited on cement 4 ¹ / ₂ hrs. d. Bit #2 in @447 ^{11.5670} Bit #3 in 2800'. 900 (77
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed (work) SEE RULE 1103. D6/30/02 Moved in & ri @8 p.m. 06/29 D7/01/02 Drilled/surve "C" w/2% CCL Nipple up & D7/02/02 Drilled/surve D7/03/02 Drilled/surve D7/05/02 Drilled/surve D7/06/02 Drilled/surve D7/06/02 Drilled/surve D7/08/02 Drilled/surve D7/08/02 Drilled/surve D7/09/02 Drilled/surve D7/09/02 Drilled/surve D7/09/02 Drilled/surve D7/09/02 Drilled/surve D7/09/02 Drilled/surve D7/09/02 Drilled/surve D7/09/02 Drilled/surve D7/10/02 Drilled/surve SIGNATURE	CHANGE PLANS	COMMENCE DRILLING CASING TEST AND CE OTHER: and give pertinent dates, inclu- cilling Co. Rig # ' 48# casing, set culated 75 sx to Drilled/surveyed illed/surveyed.	A DEPHONE NO. 915/368-14

07/11/02 Drilled/surveyed. Circulate, trip & start to run 9-5/c casing. 07/12/02 Ran 108 jts 9-5/8" casing set @4801.51'. Cemented w/1300 sx 35/65 Poz "C" w/6% gel, 5% salt & 250 sx class "C" neat. Circulated 123 sx to pit. Plug down @1:45 p.m. 07/11/02 Waited 21 hrs on cement. 07/13/02 Drilled cement, float & guide shoe. Drilled/surveyed. Bit #5 in @4825'. 07/14/02 Drilled/surveyed. 07/15/02 Drilled/surveyed. 07/16/02 Drilled/surveyed. 07/17/02 Drilled/surveyed. 07/18/02 Drilled/surveyed. Trip for bit #6, in @7385'. 07/19/02 Drilled/surveyed. 07/20/02 Drilled/surveyed. 07/21/02 Drilled/surveyed. Trip for bit #7, in @8204'. 07/22/02 Drilled/surveyed. 07/23/02 Drilled/surveyed. 07/24/02 Drilled/surveyed. 07/25/02 Drilled/surveyed. 07/26/02 Drilled/surveyed. Trip for bit #8 in @9846'. 07/27/02 Drilled/surveyed. 07/28/02 Drilled/surveyed. 07/29/02 Drilled/surveyed. 07/30/02 Drilled/surveyed. Started trip in hole for bit #9. 07/31/02 Drilled/surveyed. Trip for bit #9 in @11,592'. 08/01/02 Drilled/surveyed. Trip for hole 08/02/02 Drilled. Trip in hole to repack swivel. 08/03/02 Drilled/surveyed. 08/04/02 Drilled/surveyed. Trip for bit #10, in @12,527'. 08/05/02 Drilled 08/06/02 Drilled/surveyed. 08/07/02 Drilled 08/08/02 Drilled/surveyed. 08/09/02 Drilled/surveyed. Trip for bit #11, 7-7/8" in @13,164. Tested BOP @5000#. 08/10/02 Drilled 08/11/02 Drilled 08/12/02 Drilled Drilled/surveyed. Started logging well. 08/13/02 Finished logging well. Logger's TD 13,600'. 08/14/02 08/15/02 Running $5\frac{1}{4}$ " casing. 08/16/02 Finished running casing, circulated & cemented, set lips & cut off casing, removed BOP's & nippled up tree, jet pits. Ran 295 joints of $5\frac{1}{2}$ " 17# casing set @13,588'. Cemented with 500 sx 35/65 Poz/H+6% gel+5% salt+.1 pps celloflake+.2% antifoam+ .2% mid-temp retarder, 350 sx 50/50 Poz/H+2% ge1+.1% dispersant+.2% antifoam+.2% retarder and 200 sx class "H"+.05 gps retarder+.2 gps saltbond+.05 gps antifoam+1.6% D600 gas block. Plug down @1:30 p.m. Rig released @3:00 a.m. 08/16/02.

¥,