District I 1625 N. Fren. District II 1301 W. Grat District III 1000 Rio Bra District IV 1220 S. Franc APPL	nd Avenue, zos Road, A sis Dr., San	, Artes Aztec, nta Fe,	NM 8	188210 FE	ARTES	nergy A O A	Minerals il Conser 1220 S. Santa F	and 1 rvatic . St. F e, NN	Natura on Di Tranci 1 875	al Reso vision s Dr. 05			to appropr Stat Fe	Form C-101 ised March 17, 1999 iate District Office e Lease - 6 Copies e Lease - 5 Copies ENDED REPORT	
												-* OGR	ID Number	DA ZONE	
Fasken Oil and Ranch, Ltd. 303 West Wall, Suite 1800							800 Midla	Midland, TX 79701			151416 <sup>3</sup> API Number				
<sup>4</sup> Proper	<sup>4</sup> Property Code <sup>5</sup> Prop								erty Name			30-025-36093 Well No.			
L <u>-</u> J./_	UI +	<u>`                                    </u>	L	Kirby "26" S	state								1	No.	
UL or lot no.	Section	Tot	wnship				Irface Lo		1						
Е	26	17	'S	Range 34E	Lot Idn		Feet from 1980	No		outh line	Feet from the 1310	East/West line West		County Lea	
UL or lot no.	C +	<b>—</b>		Proposed	Bottom	Hole	Location	If D	iffere	nt Froi	m Surface				
	Section	Tow		Kange	Lot	Idn	Feet from t	the	North/So		Feet from the	East	/West line	County	
North Va	cuum Ato	oka M	°P Iorrov	roposed Pool 1						<sup>10</sup> Proposed Pool 2					
	N			Well Type Co	ode		<sup>13</sup> Cable/Ro Rotary		14 Lease Type Code 15 Ground Leve			Level Elevation			
<sup>16</sup> Mul	tiple N			<sup>17</sup> Proposed Dep	orh		<sup>18</sup> Formatio	Formation		S <sup>19</sup> C'ontractor			4032' <sup>20</sup> Spud Date		
				<u>11,800'</u> 21 ,			Morrow				Unknown		1/15/03		
Hole Size				Ig Size			ing and C	Ceme	nt Pro	ogram					
17 1/2"		13 3		lg Size	Casing weight/foot Setting			ing Dep	oth	Sacks of Cement		Es	timated TOC		
12 1/4"		9 5/			36/40#	48# 500'			550 sx C		surface		ce		
8 3/4"		5 1/2	2"		17/20#		5000'					surfa	;e		
								1,800'			1850 sx C/H		4500'		
		-	-	s application is n, if any. Use a OCEdure, ca	autional st	ram ar	nd BOP scl ermit Ex	hemat	ic. s 1 `	(car )	nt productive zone		oposed new	productive zone.	
I hereby certify the st of my knowled	that the info	ormati	ion give	en above is true	and compl	ete to th	ie	<u>1- 1-</u> 11					VISIO	T	
est of my knowledge and belief.						Аррі	OIL CONSERVATION DIVISION Approved by: ORIGINAL SIGNED BY								
rinted name: Jimmy D. Canile							Title	:	PAUL F. KAUTZ					AUTZ	
tle: Regulatory Affairs Coordinator ate: 12/20/02 Phone: (915) 687-1777						Appr	Approval Date: PETROLEUM ENGINEER Expiration Date: Expiration Date: Conditional Approximation Date: Description Date: D								
			t				Attac							H	

S
<u> </u>
1

DISTRICT 1

1685 N. French Dr., Hobbs, NM 88240 DISTRICT II 511 South First, Artesia, NM 88210

DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410

DISTRICT IV 2040 South Pacheco, Santa Fe, NM 57505

## State of New Mexico

Energy, Minerals and Natural Resources Department

Form C-102 Revised March 17, 1999

Submit to Appropriate District Office State Lease - 4 Copies Fee Lease - 3 Copies

## OIL CONSERVATION DIVISION

2040 South Pacheco Santa Fe, New Mexico 87504-2088

C AMENDED REPORT

API Num	1	,	WELL I	LOCATIO	N AND A	CRE	AGE DEDICAT	CION PLAT		D REFORT			
30-025-2		Pool Code			Pool Name								
30-025-3609-3 Property Code				86800		North Vacuum Atal							
3/0/2			Proper	ty Nam	he	Idan MCOKa MO		umber					
UGRID No.			KIRBY "2	6 5	STATE		1	umper					
151416				FASK	Operation FN OIL 2	or Nam	NCH, LTD.	Elevation					
					Sumface		NCH, LID.	4032'					
UL or lot No. Sec	tion	Township	Range	Lot Idn	Surface								
E   2	26	17 S	34 E		Feet from		North/South line	Feet from the	East/West line	County			
		L			1980		NORTH	1310	WEST	LEA			
UL or lot No.   Sect	lion	Township	rent From Su	urface									
			Range	Lot Idn	Feet from	the	North/South line	Feet from the	East/West line				
Dedicated Acres   Jo	vint or	Infill Con	nsolidation						Dest/west ine	County			
320			12011021012	Code 0	der No.			L					
NO ALLOWADI	12 107												
THE ALLOWADI	-1C 141	DR A N	SIGNED '	TO THIS	COMPLETIC	N UI	TIL ALL INTER	ESTS HAVE BE					
P			-SIAN	DARD UN	IT HAS BE	CEN A	NTIL ALL INTER PPROVED BY 1	THE DIVISION	EN CONSOLIDA	red			
	li					T		7					
	li					1		OPERATO	R CERTIFICATI				
	li							I have by certify the the iner					
	1					1		Contractient Auteur	A 15 THE and complete to the lite				
	<u>198</u>					1		best of my knowle	rage and belief.				
	li					1							
F	- #					I.	4	Kung	A aui				
	LAT	- N32*48 NG - W103	27.9			+		Signature	Center	<u> </u>			
4032.6		1032.9'	52 00.0			Jimmy D. Printed Name	Carlile						
	1				ļ								
	Ť				1			Title	y Affairs Co	oor.			
4032.3'	4	030.3'			]			December 20, 2002					
	1		l		1			Date					
	- <del> </del>							SURVEYOR	CERTIFICATIO				
	i				1			I hereby certify the	at the well location	.			
	Í				!			I was plat was p	lotted from Hats .				
	1							I being and th	de by me or und hat the same is tru	t my			
	Ì		ĺ		1			correct to the be	st of my belief.	* una			
	!							DECEMBE	R 06, 2002				
	+-		#-			_		Date Surveyed	TTO				
	1							Signature & Seal Professional Sug	levie and the second				
1	1				i				T-1				
	 				í		T.	a MA	SPAN .				
	l		i		}	- mart	1 Km	<u>`</u>					
	l		İ		-	1.0. N	<u></u>	]]					
					1		11	Certificate No. Go	In Listones 7	977			
				-				BASIN	SURVEY S	- 11			

## **Recommended Procedure**

Kirby "26" State No. 1 ------ A.F.E. No. 627 -----North Vacuum Atoka-Morrow Field 1980' FNL and 1310' FWL Sec. 26, T17S, R34E Lea County, NM

- 1. Drilling contractor to set 30" conductor if necessary. MIRU rotary tools.
- Drill 17-1/2" hole to 500' with spud mud. Set and cement 13-3/8" casing 550 sx Class "C" with 2% CaCl<sub>2</sub> (s.w. 14.8 ppg, yield 1.32 ft<sup>3</sup>/sx). WOC 18 hrs.
- 3. Drill 12-1/4" hole to 5000' with 10 ppg brine water. Control seepage with paper.
- 4. Set and cement 9-5/8" casing at 5000' with estimated 1000 sx Halliburton Interfill "C" with 8# salt and ½# Flocele (s.w. 11.9 ppg, yield 2.46 ft<sup>3</sup>/sx) plus 200 sx Class "C" neat (s.w. 14.8 ppg, 1.32 ft<sup>3</sup>/sx). Run temperature survey and locate TOC if cement is not circulated.
- 5. Install 11" x 5000 psi intermediate spool. NU 11" 5000 psi B.O.P.'s, hydril and choke manifold. WOC 12 hours. Set up DST test line complete with test tank. RU mud gas separator with flare ignitor. Install H<sub>2</sub>S monitor equipment, escape packs and briefing stations.
- Hydrostatically test 200' of 9-5/8" casing to 2800 psig, casing spool, BOP's, and choke manifold to 3000 psig, and hydril to 1500 psig. Install PVT equipment
- 8. Drill 8-3/4" hole to total depth of 11,800'. Drill out using fresh water to a depth of 9100'. Convert to 9.0 ppg cut brine water at 9100' just above the Wolfcamp shales. Mud up by 10,800' with starch and PAC mud system. Increase viscosity with salt gel or polymer as needed to clean hole. Maintain 9.0-9.5 ppg and 10 cc water loss to total depth.
- 9. DST all shows.
- 10. Log well with DLL-MSFL and CNL-LDT using Schlumberger Platform Express.
- 11. Install 5-1/2" BOP rams, run and cement 5-1/2" production casing (resin coated and centralized through pay zones) with DV tool at base of Abo (estimate 9000') as follows;

First Stage: Note, batch mix lead slurry. 10 bfw + 500 gallons Mud Clean + 10 bfw and estimated 750 sx Halliburton Super "H" with 1# salt, 0.4% CFR-3, 0.5% Halad-344, 0.1% HR-7 and 5# Gilsonite (s.w. 13.0 ppg, yield 1.60 ft<sup>3</sup>/sx). Open DV tool and circulate 6 hours.

Second stage: 1000 sx Halliburton Lite "C" with 6% gel (s.w. 12.6 ppg, yield 2.01 ft<sup>3</sup>/sx) plus 100 sx Class "H" neat (s.w. 15.6 ppg, yield 1.18 ft<sup>3</sup>/sx). Calculate second stage cement volume for TOC at 4500'.

- 12. Set slips, nipple down BOP's and run temperature survey to locate cement top.
- 13. Install 11"-5000 psi x 7-1/16"-5000 psi tubinghead and flow tree.
- 14. Rig down and move out rotary tools.
- 15. Level location, set mast anchors, move in and rig up completion unit.

Kirby "26" State No. 1 Recommended Procedure Page 2

- 16. RIW with 4-5/8" bit, 5-1/2" casing scraper, 6 3-½" drill collars and 2-3/8" 4.7# N-80 EUE 8<sup>rd</sup> tubing. Drill out DV tool and reciprocate scraper through DV tool several times. Pressure test casing to 1500 psig. RIW and clean out to float collar. Circulate well clean and pressure test casing to 1500 psig. POW and LD tools.
- 17. RIW with packer, T.O.S.S.D. with "F" profile nipple and 2-3/8" tubing. Set packer, install flow tree, swab down tubing and perforate pay interval.
- 18. Flow test well , evaluate, and stimulate if necessary.
- 19. RDPU. Clean and level location.
- 20. Run C.A.O.F.P. and pressure build up.
- 21. Connect surface equipment.

TET (Kirby26State1drlgprc)

## Recommended Casing Program A.F.E. No. 627

Fasken Oil and Ranch, Ltd.-----Kirby "26" State No. 1-----North Vacuum Atoka-Morrow Field Lea County, NM

String	Footage	Size	Weight	Grade	Thread
Surface	500'	13-3/8"	48.00#	H-40	ST&C
Intermediate	2700' 1500' <u>800'</u> 5000'	9-5/8" 9-5/8" 9-5/8"	36.00# 40.00# 40.00#	K-55 K-55 HCK-55	ST&C ST&C ST&C
Production	800' 10,000' <u>1,000'</u> 11,800'	5-1/2" 5-1/2" 5-1/2"	17.00# 17.00# 20.00#	N-80 N-80 N-80	BT&C LT&C LT&C
Tubing	11,700'	2-3/8"	4.70#	N-80	EUE 8rd

