


SCOUT REPORT
NEW MEXICO
OIL CONSERVATION COMMISSION

Way
~~11-13~~
West Sea Oil Co



Company ~~Texaco~~ *West Sea Oil Co*

Farm Name _____ Tex State _____ Well No. *1-A*

Land Classification _____ State _____

Sec. *16* Twp. *20* Range *32* County *Lea*

Feet from Line: _____ N. *1980* S. _____ E. *1980* W. _____

Elevation _____ Method _____

Contractor *Peck and Croft* Scout _____

Spudded *9-4-39* Completed *10-15-39* Initial Production _____

Bond Status *1-11-40*

Amount
Casing and Cementing Record

Size	Feet	Inches	Sax Cement
<i>8 1/2</i>	<i>958</i>		<i>3</i>
<i>6 5/8</i>	<i>2593</i>		<i>100</i>

Tubing Record

<i>7"</i>	<i>7600</i>
-----------	-------------

ACID RECORD

Gals.	Top Pay	TD

TA	<i>813</i>
TS	
BS	<i>1526</i>
TRS	<i>1357</i>
TBL	<i>74</i>
TWL	

SHOOTING RECORD

No. of Quarts	Shot at	Feet
<i>S/O</i>	<i>S/O</i>	<i>S/O</i>
<i>S/O</i>	<i>S/O</i>	<i>S/O</i>

DATE		DATE	
<i>9-13</i>	<i>RUM</i>	<i>11-7</i>	<i>✓</i>
<i>SEP 20 1939</i>	<i>4446 RR</i>	<i>NOV 8 - 1939</i>	<i>✓</i>
<i>SEP 27 1939</i>	<i>61660 X</i>	<i>11-15</i>	<i>✓</i>
<i>OCT 4 - 1939</i>	<i>7485 L</i>	<i>NOV 22 39</i>	<i>✓</i>
<i>OCT 11 1939</i>	<i>TD 2629 L</i>	<i>NOV 28 39</i>	<i>TD 2629 h Rigged up Pump</i>
	<i>1600' O.I.H. 2 HTS</i>	<i>DEC 6 39</i>	<i>✓</i>
	<i>1500' O.I.H. 6 HTS</i>	<i>DEC 13 39</i>	<i>✓</i>
<i>OCT 18 1939</i>	<i>Testing - Plug 7"</i>	<i>DEC 20 39</i>	<i>✓</i>
<i>OCT 25 1939</i>	<i>TD 2629 L</i>	<i>DEC 28 39</i>	<i>✓</i>
	<i>1050 BO 17 HTS (Swab)</i>	<i>JAN 4 40</i>	<i>✓</i>
	<i>Spout in for storage</i>	<i>JAN 10 40</i>	<i>✓</i>
	<i>To R/L pump</i>	<i>JAN 17 40</i>	<i>✓</i>
		<i>JAN 24 40</i>	<i>✓</i>

ILLEGIBLE

100

Depth	Formation	Depth	Formation
JAN 2-190	[Handwritten mark]		
FEB 7 -90	V ✓		
FEB 14-90	V ✓		
FEB 21-90	TD 768' L		
	IP Pump 194 BO 76 hrs		

Ray get gauge See me Norma.

REC'D - 8 NOV
 1990