

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
E-6568

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator JFG Enterprise	8. Farm or Lease Name Phillips State
3. Address of Operator P.O. Box 100, Artesia, NM 88211-0100	9. Well No. 1
4. Location of Well UNIT LETTER <u>G</u> , <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>2310</u> FEET FROM THE <u>East</u> LINE, SECTION <u>16</u> TOWNSHIP <u>20S</u> RANGE <u>32E</u> NMPM.	10. Field and Pool, or Wildcat Halfway Yates
15. Elevation (Show whether DF, RT, GR, etc.) 3516 DF	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐
OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 3-16-87 Tag bottom @ 2674' - Pump 20 sack Plug Class C w/Calc. @ 2644' - wait 2 1/2 hrs. Tag plug @ 2544' (100' fill).
- 3-17-87 Ran tubing back in hole to 2544' - Pump 30 sack Plug Class C w/Calc. Shut down.
- 3-18-87 Tag top of plug @ 2158' - Go in hole w/tubing. Pump 100 sack Plug Class C Pull 40 jts. 2" tubing - Pump 100 Sack Plug Class C - Pull 329' 4 1/2" Casing, Shut down.
- 3-19-87 Tag top of plug @ 325' - Go in hole w/tubing & pump 75 sack Plug Class C w/Calc. - Pull out of hole - Casing full & holding. - Set Dry Hole Marker. Rig down. Total Cement: 325 Sacks Class C.
- 3-23-87 Haul tubing and rods to yard. Will start clean-up 4-1-87.

NOTE: Plugging operation witnessed by New Mexico Oil Commission Representative - Ray Smith.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED _____ TITLE Agent DATE 3-25-87

APPROVED BY R. A. Smith TITLE OIL & GAS INSPECTOR DATE JAN - 4 1988

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
MAR 26 1987
OCD
HOBBS OFFICE