

(SUBMIT IN TRIPLICATE)

Land Office New MexicoLease No. NR 110957Unit Little Lady

UNITED STATES

DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 29, 1963

Well No. 1 is located 650 ft. from [N] line and 1900 ft. from [E] line of sec. 18

NE 10 (1/4 Sec. and Sec. No.) 20 S (Twp.) 13E (Range) 111N (Meridian)
Salt Lake (Field) Lee (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 3500 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

8/13/62 Rigging up cable tools.
8/14/62 Drilling out cement plug.
8/15/62 Cleaned out to 130' open hole.
8/16/62 Ran 130 feet 10 3/4" pipe.
8/17/62 Cleaning out to 140'.
8/18/62 Cleaning out to 160'.
8/19/62 Cleaning out to 315' lower 10 3/4" pipe.
8/20/62 Cleaning out to 370' lowered 10 3/4" pipe.
8/21/62 Cleaning out to 425' lowered 10 3/4" pipe.
8/22/62 Cleaning out to 460' lowered 10 3/4" pipe.
8/23/62 Cleaning out to 495' lowered 10 3/4" pipe.
8/24/62 Cleaning out at 515' key seat 505 - 515.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company RANDALL F. MONTGOMERYAddress P.O. Box 2414Mobbe, New MexicoBy R. F. Montgomery
RANDALL F. MONTGOMERY
Title Operator

8/25/62 Iron in hole @ 498 clean out to 520.
 8/26/62 Clean out to 530 trying to recenter stub @ 5/8/
 8/27/62 Drilled by side @ 5/8 filled back w/rocks.
 8/28/62 Pulled 10 1/4" pipe from 468 and run hole with 12 1/2" bit to 465.
 8/29/62 Cleaning out at 475. Wood block fell in on tools from the open hole section
 hung up tools. Out line and fishing for tools.
 8/30/62 Fished out 12 1/2" tools clean out to 465.
 8/31/62 Cleaning out from 485 to 528.
 9/1/62 Cleaning out from 528 to 531 running on iron. Broke down 12 1/2" tool, made
 up 6 1/2" tools.
 9/2/62 Ran 25 joints 10 1/4" eng. (529.94') cleaning out at 531, running and pump
 getting out iron.
 9/3/62 Running sand pump at 531 getting out iron.
 9/4/62 Running sand pump 532 - 534 and magnet to clean out iron.
 9/5/62 Running wedge, magnet and sand pump getting out iron 534 to 550.
 9/6/62 Cleaning out iron. Ran @ 5/8 impression block at 550. Ran 6" impression
 block at 550.
 9/7/62 Cleaning out 550 - 562. Running sand pump for iron.
 9/8/62 Cleaning out iron 562 - 565. Running sand pump and magnet.
 9/9/62 to 9/11/62 Shut in waiting on orders.
 9/11/62 Cleaning out 565 - 585.
 9/12/62 Cleaning out 585 - 589. Ran out of @ 5/8.
 9/13/62 Rig cable tool down waiting on orders.

Temporary shutdown. Request permission to leave well in its present
 status pending decisions of manner of completing and observing of wells
 presently producing on lease.