

UNITED STATES **RECEIVED**
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
MAR 20 2 17 PM '96

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—B" for such proposals.

SUBMIT IN TRIPLICATE

1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other	5. Lease Designation and Serial No. NM-0250
2. Name of Operator ARMSTRONG ENERGY CORPORATION	6. If Indian, Altonce or Tribe Name
3. Address and Telephone No. P. O. Box 1973, Roswell, New Mexico 88202-1973 623-8726	7. If Unit or CA, Agreement Designation
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 2086' FSL and 556' FWL Section 1, T-20S, R-34E	8. Well Name and No. K. F. Quail
	9. API Well No. 1
	10. Field and Pool, or Exploratory Area South Lea San Andres
	11. County or Parish, State Lea County, New Mexico

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input checked="" type="checkbox"/> Other Casing Integrity Test
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Operator proposes to perform a Casing Integrity Test with 24 hours notification to BLM using the following procedures:

- Step 1: Move in location, rig up and set up BOP.
Step 2: Pull rods and tubing.
Step 3: Set bridge plug @ 5350'.
Step 4: Displace casing with inhibited fluids. Pressure casing up to 500 psi for 30 minutes.

14. I hereby certify that the foregoing is true and correct

Signed [Signature] Title President Date March 18, 1996

(This space for Federal or State office use)

Approved by [Signature] Title PETROLEUM ENGINEER Date 4/2/96

Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See instruction on Reverse Side