

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE  
(Other instructions on  
reverse side)

Form approved.  
Budget Bureau No. 42-R1424.  
5. LEASE DESIGNATION AND SERIAL NO.

NM-0250

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		6. IF INDIAN, ALLOTTEE OR TRIBE NAME -	
2. NAME OF OPERATOR TEXACO Inc.		7. UNIT AGREEMENT NAME -	
3. ADDRESS OF OPERATOR P. O. Box 728 - Hobbs, New Mexico 88240		8. FARM OR LEASE NAME K.F. Quail Fed.	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 2086' FSL & 556' FWL of Section 1, T-20-S, R-34-E, Unit Letter 'L', Lea County, New Mexico.		9. WELL NO. 1	
14. PERMIT NO. Regular		10. FIELD AND POOL, OR WILDCAT Lea Bone Springs	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3698' (DF)		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 1, T-20-S, R-34-E	
		12. COUNTY OR PARISH Lea	
		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other)	See Below		X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
(Other)			

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Texaco Inc. proposes to abandon the Lea Bone Springs and recomplete in the Cherry Canyon Zone as follows:

1. Rig up. Install EOP.
2. Run free-point survey. Cut & pull 2-7/8" casing at depth determined by survey.
3. Plug back to 7000' to abandon Lea Bone Springs zone by setting CIBP w/50' cement on top of plug.
4. Clean out open hole from 5490' to PBTD.
5. Set 7" OC liner from PBTD to 5490' (approx 1600'). Circulate cement.
6. Drill out cement. Log well.
7. Perforate 7" OD csg liner w/1 JSPF every other foot from 6895-6940'.
8. Set packer @ approx. 6840'. Spot 100 gal 15% NE acid across perforations.
9. Acidize perforations w/4000 gals. 15% NE acid in 4 equal stages using 15 Ball Sealers after each stage.
10. Install pumping equipment, test and place on production.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Asst. District Supt. DATE 2-1-77

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

